


GM Goodwrench Engines Catalog

August 2004



Goodwrench Engines

TABLE OF CONTENTS

Click on any of the following sections or sub-sections to link directly to the information.

Section I	INTRODUCTION.....	2
Section II	COMPONENT PARTS SPECIFICATION	
	Goodwrench Service Replacement Engines (New/Reman)	3
	RPO Listings	5
Section III	GENERAL INSTALLATION INSTRUCTION.....	8
Section IV	GENERAL ENGINE DIAGNOSTICS.....	17
Section V	GOODWRENCH SERVICE REPLACEMENT ENGINES.....	30
	Application Content & Installation Procedures	
	<i>4-Cylinder Engine Family - Gasoline</i>	
	2.2L	31
	2.3L	35
	2.4L	41
	2.5L	42
	<i>Straight 4 In-Line Engine Family - Gasoline</i>	
	2.8L	62
	<i>Straight 5 In-Line Engine Family - Gasoline</i>	
	3.5L	64
	<i>V6 Engine Family - Gasoline</i>	
	2.8L	66
	3.1L	68
	3.3L	72
	3.4L	74
	3.5L	77
	3.6L	78
	3.8L	79
	4.3L	88
	<i>Straight 6 In-Line Engine Family - Gasoline</i>	
	4.2L	104
	<i>V8 Engine Family - Gasoline</i>	
	4.0L	106
	4.3L	107
	4.6L	108
	4.8L	111
	5.0L	112
	5.3L	114
	5.7L	115
	6.0L	124
	7.0L	129
	7.4L	131
	8.1L	134
	<i>V8 Engine Family - Diesel</i>	
	6.5L	137
Section VI	PART NUMBER INDEX.....	140
Section VII	COMMENT & FEEDBACK.....	145

INTRODUCTION

HOW TO USE THIS REFERENCE GUIDE

Your new 2004 Goodwrench Engine Reference Guide contains a quick reference section and a color-coded index that is exclusive for each section of this book. Listed below are explanations of the format for each individual section.

QUICK REFERENCE INFORMATION

This section is located at the beginning of this reference guide. This section contains everything that you need to know about warranty, component parts specifications for new and remanufactured engines, general installation procedures, general engine diagnostics, and core return procedures.

ENGINE FAMILY APPLICATION, CONTENT AND INSTALLATION*

This portion of the catalog contains engine-specific content, application information, and any additional installation instructions needed for a particular engine. The quickest method in finding a particular engine would be to refer to the color-coded index (if liter sequence is known). All part numbers are numerically listed in each color-coded section. Also, there is a color-coded index guide on the outer back cover of this book. However, if the liter is unknown, a part number sequence listing is available in the index of this reference guide.

Red = this section contains all 4-cylinder engines

Green = this section contains all V6 and I6 engines

Blue = this section contains all V8 gasoline and diesel engines

REPLY CARD

We would like to hear from you. Please fill out the reply card and tell us what you think about the Goodwrench Engine Reference Guide and product offerings.

*For additional assistance on engine content or installation, contact PARTECH at 1-800-433-6961.

COMPONENT PARTS SPECIFICATIONS

GOODWRENCH REMANUFACTURED ENGINES

This is a generic summary of the type of parts found in Goodwrench remanufactured engines. Each engine family is different from other engine families, and remanufacturing specifications can be unique to a specific engine part number.

New Components are those that are always installed new (OE designed) during the remanufacturing process.

Qualified Components are those used parts that are reclaimed by cleaning and checking to OE specifications.

Remanufactured Components are those used parts that are reclaimed by machining to specifications established by GMSPO Engineering with the consultation and direction of General Motors Powertrain (GMPT) Engineering. Changes to OE specifications are typically validated by dynamometer durability testing. All GMSPO remanufactured parts are shipped clean and ready for installation unless otherwise noted in the installation instructions.

THE USE OF SURFACE CONDITIONING DISKS TO REMOVE THE BLACK OXIDE FINISH OR GASKET MATERIAL ON SEALING SURFACES IS STRICTLY FORBIDDEN AND MAY LEAD TO PREMATURE BEARING FAILURE.

COMPONENT SUMMARY LIST

NEW COMPONENTS	QUALIFIED COMPONENTS
Bearings - All	Balance Shafts
Bolts - Cylinder Head (typically)	Ball-Rocker Arm
Camshaft (flat lifter only)	Bracket - Engine Lift
Cup Plugs and Freeze Plugs	Caps (valve)
Gaskets - All	Cover - Fuel Pump Opening
Gear - Balance Shaft Drive (typically)	Fasteners - Various
Gear - Balance Shaft Driven (typically)	Front Covers (if applicable)
Flat Lifters	Intake Manifold (if applicable)
Nut-Connecting Rod	Oil Fill Cap
Nut - Rocker Arm Stud	Oil Pan
Oil Pump	Pushrods
Pistons & Pin and Rings	Retainer - Lifter
Seals - All	Rocker Arms
Sprocket - Camshaft and Crankshaft	Rocker Covers (if applicable)
Timing Chain	Rotators (valve)
Valve - Oil Filter Bypass	Shaft - Distributor to Oil Pump
Valves - Inlet and Exhaust	Valve Springs

COMPONENT PARTS SPECIFICATIONS

GOODWRENCH REMANUFACTURED ENGINES

COMPONENT SUMMARY LIST cont.

REMANUFACTURED COMPONENTS	Attribute	Differs from OE Specifications
Cylinder Block	Balance Shaft Bore	Same as OE Specifications
	Camshaft Bore	Same as OE Specifications
	Cylinder Bore	Typically .010", .020" up to .030" oversize, same surface finish and geometry as OE - varies by engine family.
	Deck Height	Same to .010" under OE.
	Head Gasket Surface	Same (including flatness, surface finish, etc. - may be machined to achieve OE spec).
	Lifter Bore	Same as OE Specifications
	Main Bearing Bore	Honed to OE specs.*
	Other	Welding permitted for cosmetic purposes - no welding in cylinder bore. Thread repair (Heli-coli or Time-sert) is permitted.
Cylinder Head	Head Gasket Surface	Same (including flatness, surface finish, perp, etc. - may be machined to achieve OE spec).
	Valve Guides	Same surface finish and geometry.
	Valve Seats	Reconditioned to OE specifications - replaced when necessary.
	Other	Thread repair (Heli-coli or Time-sert) is permitted with limits. Cosmetic welding is permitted except in the combustion chamber area.
Crankshaft	Main and Rod Journals	.010", .020", possibly .030" undersize (Dia) - varies by engine family - same surface finish and geometry.
	Other	No welding or straightening allowed.
Camshafts (Roller Lifter Only)	Lobes	Roller lifter camshafts polished and qualified to OE specifications, no rework allowed.
Connecting Rods	Diameter of Big End	Parting line may be machined (max .030") and big end honed. Keep center to center distance to OE specification.

**Assembly information -OE bearing clearances are maintained. Fasteners are tightened in sequence and torques.*

COMPONENT PARTS SPECIFICATIONS

RPO LISTING - ENGINES

RPO	MY	RPO Description
LA1	96-02	6 Cyl, 3.4L, MFI, HO
LA5	83-86	1.8L (1.8J), L4, MFI
LA7	85-86	1.5L (1.5-5), L4 (Diesel)
LA9	96-02	4 Cyl, 2.2L, MFI, DOHC
LB1	85-92	4.3L (4.3N), V6
LB4	82-97	(4.3Z), V6, EFI
LB4	85-98	(4.3L), V6 90 DEG Gas TBI
LB6	85-90	2.8L (2.8W), V6, EFI
LB7	01-02	Diesel, 8 Cyl 6.6-1, V8, DI, Turbo, HO, Isuzu
LB8	85-89	2.8L (2.8S), V6, MFI
LB9	82-83	5.0L (5.0F), V8, EFI
LC0	86-89	1.5L (1.5-9), L4 (Turbo) MFI
LC1	82-84	2.8L (2.8-1), V6, 2BBL, HO
LC2	86-87	3.8L (3.8-7), V6, SFI, HO/Turbo
LC2	89-89	3.8L (3.8-7), V6 (Turbo), SFI, HO/Turbo
LC3	80-82	229 C.I.D. (229K), V6, 2BBL
LC3	83-84	229 C.I.D. (229-9), V6, 2BBL
LC4	80-85	4.1L (4.1-4), V6
LC5	78-78	231 C.I.D. (231G), V6
LC5	85-85	1.5L (1.5K), L4, 2BBL
LC5	86-89	1.5L (1.57), L4, 2BBL
LC6	78-79	231 C.I.D. (231-2), V6, 2BBL
LC7	87-88	4.1L (4.1-7), V8
LC8	78-82	231 C.I.D. (231-1), V6, 4BBL Turbo
LC8	83-83	231 C.I.D. (231-8), V6, 4BBL Turbo
LC9	78-79	196 C.I.D., V6, 2BBL
LC9	85-88	1.6L (1.6-4), L4, 2BBL
LD2	85-96	2.3L (2.3D), L4, DOHC
LD2	93-96	2.3L (2.3G), L4, DOHC, U-Van, Export
LD4	78-78	250 C.I.D., Stan 6 Cyl
LD4	87-95	2.3L (2.3D), L4, DOHC
LD5	76-87	231 C.I.D., (231A), V6, 2BBL
LD7	75-77	231 C.I.D., (231C), V6, 2BBL
LD8	93-02	8 Cyl, 4.6L, V8, DOHC, SFI, (281 C.I.D.)(Northstar)
LD9	96-02	4 Cyl, 2.4L, SFI, DOHC
LE2	80-80	2.8L (2.8X), V6, 2BBL
LE2	81-86	2.8L (2.8X), V6, 2BBL
LE3	79-84	250 C.I.D., L6
LE4	80-80	400 C.I.D. (400X), V8, 4BBL
LE4	92-94	2.0L (2.0H), L4, MFI, OHC, 122 C.I.D.
LE8	76-91	7.4L-W, V8, 454 C.I.D., 4BBL
LE8	01-01	2.5L, V6
LE8	87-87	454, 7.4L, V8, 4BBL (different int & exh manifold)
LE9	81-86	305 C.I.D. (305H), 5.0L, V8
LF3	81-86	V8, 5.0L-F, 305 C.I.D., 4BBL
LF3	86-86	305, V8, TBI
LF4	76-80	400 C.I.D. (400R), V8, 4BBL
LF5	79-91	350 C.I.D., V8, 5.7L-P, 2BBL

RPO	MY	RPO Description
LF5	92-00	350 C.I.D., V8
LF6	96-02	6 Cyl, 4.3L, CPI, V6, 90 DEG
LF7	79-79	260 C.I.D. (260P), Diesel V8
LF8	76-80	454 C.I.D. (454S), V8
LF9	78-85	350 C.I.D. (350N), Diesel V8
LG0	85-95	2.3L (2.3A), L4, MFI
LG0	91-91	2.3L (2.3A), LA (high output), OHC
LG1	96-96	2.4L, MFI, SOHC, 4 Cyl
LG1	01-02	2.4L, MFI, SOHC, 4 Cyl
LG2	86-88	3.8L (3.8B), V6, SFI
LG3	76-76	305 C.I.D. (305Q), V8
LG3	77-78	305 C.I.D. (305U), V8
LG3	79-79	305 C.I.D. (305G), V8
LG3	86-88	3.8L (3.8-3), V6, SFI, HO, 231 C.I.D.
LG3	01-02	262 C.I.D. (4.3L), V6, OEM
LG4	78-88	305 C.I.D. (305H), V8-Pass
LG5	89-90	3.1L (3.1V), V6, EFI
LG6	87-96	3.1L (3.1D), V6, TBI
LG7	85-94	3.3L (3.3N), V6, MFI
LF7	02-02	305 C.I.D. (5.0L), V8, OEM
LG8	84-84	5.0L, V8
LG8	85-90	5.0L (5.0-9), V8 (HI Output)
LG8	99-02	6 Cyl, 3.1J, SFI, V6
LG9	76-81	305 C.I.D. (305G), V8
LH0	88-96	3.1L (3.1T), V6, MFI
LH0	90-94	3.1L (3.1T), V6, Export
LH0	92-94	3.1L (3.1T), V6, Export
LH7	81-84	2.8L (2.8Z), V6 (HI Output), 2BBL
LH8	82-86	1.8L (1.8-0), L4, TBI
LH8	85-86	1.8L (1.8-0), L4, EFI
LH9	91-95	250 C.I.D. (4.1L), 6 Cyl
LJ5	81-86	1.8L (1.8D), Diesel L4
LK9	82-85	3.0L (3.0E), V6, 2BBL
LL1	83-84	2.8L (2.8L), V6
LL2	82-83	2.8L (2.8R), V6
LL2	90-93	2.8L (2.8R), V6
LL6	96-00	6 Cyl, 3.0L, MFI, DOHC, V6, HO
LL7	99-01	4 Cyl, 2.0L, MFI, DOHC, Turbo, HO
LL8	87-89	2.0L (2.0-1), L4 (HI Output)
LL8	01-02	4.2L, DOHC, L, MFI, Alum 6 Cyl
LM1	76-82	350 C.I.D. (350L), V8
LM1	83-88	350, V8
LM3	90-93	2.2L (2.2G), L4, TBI
LM4	02-02	8 Cyl, 5.3L, SFI, Alum
LM7	99-02	8 Cyl, 5.3L, MFI
LM9	84-86	3.8L (231-9), V6, SFI, Turbo
LN2	91-02	4 Cyl, 2.2L-4, MFI, 133 C.I.D.
LN3	84-85	3.8L (231-3), V6, MFI

COMPONENT PARTS SPECIFICATIONS

RPO LISTING - ENGINES

RPO	MY	RPO Description
LN3	88-92	3.8L (3.8C), V6, MFI
LN3	99-00	3.8L (3.8H), V6, MFI
LN4	97-99	Diesel, 6 Cyl, 7.1L, Turbo
LN7	85-88	3.0L (3.0L), V6 (HI Output), MFI
LN8	83-94	2.5L (2.5E), L4, EFI
LN8	85-91	2.5L (2.5E), L4, TBI
LP2	89-01	1.0L (1.0-6), L3 (Digital Fuel Injection)
LP3	75-77	5.7L-E, 350 C.I.D., 4BBL
LP4	97-02	8 Cyl, 7.4L (7.4D), MFI
LP9	84-85	5.7L (SEO), V8
LQ0	96-98	4Cyl, 2.6L, MFI, Isuzu
LQ1	91-99	3.4L (3.4X), MFI, OHC, V6, HO, DOHC
LQ2	83-85	2.0L (2.0Y), L4
LQ4	98-02	8 Cyl, 6.0L, MFI
LQ5	82-86	2.0L (2.0P), L4, TBI
LQ6	87-92	4.5L (4.5-8), V8 (Digital Fuel Injection)
LQ7	82-85	2.2L (2.2S), Diesel L4
LQ8	82-83	2.5L (2.5F), L4, 2BBL
LQ9	81-86	2.5L (2.5-2), L4, TBI
LQ9	01-02	6.0L (6.0N), V8, MFI, Iron, High Output
LR0	90-99	7.0L, 8 Cyl
LR1	82-85	1.9L (1.9A), L4
LR2	82-90	2.8L (2.8B), V6
LR4	99-02	8 Cyl, 4.8L, MFI
LR6	88-89	4.5L (4.5-5), V8 (Digital Fuel Injection)
LR6	90-90	4.5L (4.5-5), V8, MFI
LR8	82-93	2.5L (2.5R), L4, TBI
LR9	82-84	2.0L (2.0B), L4, 2BBL
LR9	85-86	2.0L (2.0P), L4, EFI
LS0	88-00	V8, 6.0L
LS1	97-02	8 Cyl, 5.7L, SFI, Alum
LS2	85-86	4.3L (4.3-7), Diesel V6
LS3	87-93	1.0L (1.0-2), L3 Turbo
LS4	76-76	8 Cyl, 7.4L, 4BBL
LS5	80-81	4.3L (4.3S), V8, 2BBL
LS5	89-95	1.6L (1.6U), L4, TBI, OHC, 98 C.I.D.
LS6	01-02	8 Cyl, 5.7L, SFI, Alum, High Output
LS6	78-79	4 Cyl, 2.5L, 2BBL
LS8	79-79	151 C.I.D., L4, 2BBL
LS9	76-86	350 C.I.D. (350L), V8
LT1	92-98	8 Cyl, 5.7L (5.7P), MFI, HO
LT2	83-92	2.0L (2.0K), L4, EFI
LT3	87-90	2.0L (2.0M), L4, MFI
LT4	76-76	8 Cyl, 6.6L, 4BBL
LT4	96-96	8 Cyl, 5.7L, MFI, High Output
LT4	97-99	8 Cyl, 5.7L, MFI
LT5	89-96	5.7L (5.7J), TPI
LT6	79-85	4.3L (4.3V), Diesel V6

RPO	MY	RPO Description
LT6	82-84	4.3L (4.3V), Diesel V6
LT7	82-85	4.3L (4.3T), Diesel V6, 260 C.I.D.
LT8	82-87	4.1L (4.1-8), V8
LT9	80-89	350, V8
LU2	85-91	4.3B (4.3B), V6 HI Output
LU3	02-02	6 Cyl, 4.3L, MFI, V6, 90 DEG
LU4	99-01	4 Cyl, 2.3L, MFI, Low Pressure Turbo, DOHC
LU5	82-82	5.0L (5.07), V8, 305 C.I.D., TBI
LU5	83-83	5.0L (5.0S), V8, 305 C.I.D., TBI
LU8	80-81	4.9L, Turbo Charged, 301 C.I.D., 4BBL, F-car only
LV2	80-90	307 C.I.D. (307Y), V8, 5.0L, 4BBL
LV2	83-84	307 C.I.D. (307-9), V8, HI Output Thrust (W/W40)
LV4	91-93	1.6L (1.6-8), L4, DOHC Turbo
LV6	90-02	4 Cyl, 1.8L (1.8-8), MFI
LV8	75-81	260 C.I.D., V8, 4.3L-F, 2BBL
LV8	82-82	260 C.I.D. (260-8), V8
LW0	88-93	1.6L (1.6-5), L4, DOHC
LW2	90-90	4.5L (4.5-3), V8, MFI
LW5	99-01	3.0L, MFI, V6, Turbo, DOHC, Opel
LW6	91-01	4Cyl
LW9	80-83	2.5L (2.5-5), L4, 2BBL
LX0	90-02	Diesel, 6 Cyl, 6.6L, L6, Turbo
LX2	72-76	V8, 500 C.I.D., 8.2L, 4BBL
LX2	91-00	8.2L (8.2), V8, TBI
LX3	76-77	1.4L-1, L4
LX5	98-02	6 Cyl, 3.5H, MFI, DOHC, V6
LX6	77-78	151 C.I.D., L4, 2BBL
LX8	78-80	2.5L (2.5V), L4, 2BBL, 151 C.I.D.
LY5	76-78	1.6L (1.6E), L4
LY8	98-01	4 Cyl, 1.3L, MFI, OHC
LY9	85-85	1.0L (1.0M), L3
LY9	86-88	1.0L (1.0-5), L3
L01	88-01	1.6L (1.6-6), L4, MFI, SOHC
L03	88-93	5.0L (5.0E), V8, TBI
L03	87-96	5.0L (5.0H), V8, TBI
L05	89-93	5.7L, EFI
L05	91-97	5.7L (5.7-7), 8 Cyl
L05	87-96	5.7L, TBI
L09	94-97	6 Cyl, 2.5L, Fuel Injection
L11	75-77	140 C.I.D. (140), OHC, L4
L13	75-76	140 C.I.D. (140), L4
L17	78-79	1.6L (1.6E), L4, 1BBL
L17	80-81	1.6L (1.6-9), L4
L17	82-87	1.6L (1.6C), L4, 2BBL
L18	79-80	4 Cyl, 1.6L-0, 2BBL
L18	00-02	8 Cyl, 8.1L, MFI, 496 C.I.D.
L19	82-99	7.4L (7.4N), V8, EFI
L21	98-01	8 Cyl, 7.4L (7.4B), MFI, Performance

COMPONENT PARTS SPECIFICATIONS

RPO LISTING - ENGINES

RPO	MY	RPO Description	RPO	MY	RPO Description
L22	74-86	250 C.I.D. (250), L6	L54	86-86	Diesel, 4.3L (4.3-8), V8
L25	75-96	292 C.I.D. (292T), L6	L56	88-00	Diesel, 8 Cyl, 6.5 (6.5S), Turbo
L26	78-79	200 C.I.D., V6	L57	87-02	Diesel, 8 Cyl, 6.5L(6.5Y), HO
L26	91-96	4.9L (4.9B), V8, MFI	L57	94-01	Diesel, 6.5L (6.5Y), V8
L27	90-95	3.8L, SFI, V6, HO, 231 C.I.D.	L61	80-84	368 C.I.D. (368), V8
L27	77-79	4.9L (301Y), 301 C.I.D., 2 BBL, V8	L61	99-02	2.2L, 4 Cyl, MFI, DOHC - Lotus Car
L29	91-01	8 Cyl, 7.4L, MFI	L62	80-85	368 C.I.D. (368-9), V8
L30	76-76	8 Cyl, 5.0L, CPI	L65	76-77	350 C.I.D. (350G), V8
L30	95-02	8 Cyl, 5.0L, CPI	L65	85-02	Diesel, 6.5L (6.5F), Turbo, HI Output
L31	93-02	8 Cyl, 5.7L, CPI	L67	91-02	3.8L (3.8-1), SFI, V6, Super-charged
L32	75-77	350 C.I.D., 5.7L-H, V8, 2BBL	L68	85-91	2.5L (2.5U), L4, TBI
L32	93-95	3.4L, V6 (3.4S), SFI, OHV	L69	83-83	5.0L (305-7), V8, HI Output, 4BBL
L33	77-79	425 C.I.D. (425), V8	L69	84-88	5.0L (305G), V8, HI Output, 4BBL
L34	99-02	2.0L, MFI, DOHC, 4 Cyl	L72	92-97	4 Cyl, 1.3L, TBI
L34	76-82	350 C.I.D. (350R), V8	L73	88-93	1.6L (1.6-6), L4, TBI
L35	78-79	425 C.I.D. (425), V8, EFI	L74	73-76	455 C.I.D., 4BBL
L35	85-02	4.3L (4.3W), CPI, V6, 90 DEG	L75	72-76	455 C.I.D., 4BBL
L36	95-02	6 Cyl, 3.8K, MFI, V6, HO	L76	76-77	350 C.I.D., V8, 4BBL
L37	93-02	4.6L, V8, DOHC, SFI, 281 C.I.D. (Northstar)	L77	74-77	350 C.I.D. (350J), V8
L37	78-81	301 C.I.D., 4.9L (4.9W), V8, 4BBL	L77	78-80	350 C.I.D. (350X), V8
L38	83-94	2.5L (2.5A), 4 Cyl	L77	81-81	350 C.I.D. (350B), V8
L39	79-82	267 C.I.D. (267J), V8	L78	76-79	400 C.I.D., V8, 4BBL
L40	92-96	4 Cyl, 2.3L (2.3-3), MFI, SOHV	L80	77-79	403 C.I.D. (403), V8
L43	79-90	V8, 427 C.I.D., 7.0L, W/4BBL Carb	L81	81-81	V8, 5.7L
L44	85-88	2.8L (2.8-9), V6, HI Output, MFI	L81	97-02	6 Cyl, 3.0L, MFI, HO
L46	82-82	1.8L (1.8G), L4	L82	73-82	350 C.I.D. (350), V8, Special HI Perf
L47	94-01	8 Cyl, 4.0L, SFI, DOHC	L82	93-99	3.1L (3.1M), 6Cyl, V6, MFI, HO
L48	77-80	350 C.I.D. (350), V8, 4BBL	L83	82-82	5.7L (5.7-8), V8, TBI
L49	78-80	350 C.I.D. (350B), V8	L83	84-84	5.7L (5.7-8), V8, CFI - Crossfire, TBI
L49	82-82	5.7L, V8	L98	85-92	5.7L (5.7-8), 350 C.I.D., TPI
L49	84-96	Diesel, 6.5L (6.5P), V8	L99	94-97	8 Cyl, 4.3L, MFI

GENERAL INSTALLATION PROCEDURES

WARNING!

When cleaning gasket sealing surfaces on new and remanufactured engines and/or cleaning parts from the failed engine to be reused, the use of surface conditioning discs that contain abrasives, such as aluminum oxide, may cause premature bearing failure.

THE USE OF SURFACE CONDITIONING DISCS IS STRICTLY FORBIDDEN.
(i.e., SCOTCH BRITE™, ROLO BRISTLE DISCS™, Soc Att™, ABRASIVE DISCS)

If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler must be replaced. If the vehicle is equipped, the oil lines must be removed from the vehicle and thoroughly flushed or replaced. Warranty data show that more than half of all warranty claims for premature failures are associated with lack of proper lubrication. **Failure to perform these repairs will void your Goodwrench Engine Warranty.**

Before installing any engine, verify that you have the correct engine for the application. Refer to the appropriate Vehicle Chassis Service manual for proper repair procedures and specifications (i.e., fastener torque, torque sequencing, ignition timing, valve adjustment, coolant fill, air purge and fluid volumes).

Some engines have been remanufactured subsequent to the model year of the vehicle and may contain design refinements not included in the original service information (i.e., 1989 engines may incorporate design features normally found in newer models). If future service is necessary for the engine, consult the GM Parts Catalog, GM Part and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

GENERAL INSTALLATION PROCEDURES

TRANSFERABLE ENGINE COMPONENTS

Take out the old engine, mount it on an engine stand, and carefully remove those components that are to be transferred to the new engine. The following list of components should be removed and inspected for wear and damage. If the components are damaged or were the cause of the original engine failure, they should be replaced.

- **Harmonic Balancer**

- Many times, the harmonic balancer's sealing surface is damaged or warped. The balancer should be carefully inspected and, if necessary, replaced to prevent a leak in the front cover seal.

- **Intake Manifold**

- Inspect the intake manifold's machined surfaces for flatness using a straight edge. If the manifold is warped or the machined sealing surfaces are damaged, it may not seal properly, allowing water and other contaminants to enter the combustion chamber or lubricating system.
- Check for cavitation erosion or pitting.
- Check for obstructions or carbon in the internal EGR or exhaust crossover passages. Check for cracks at the bolt holes and the sensor mounting holes.
- Always clean the intake manifold thoroughly before placing it on the new engine. Any foreign objects within the intake manifold could be drawn into the combustion chamber and cause considerable damage to the pistons, valves, heads and other vital parts of the engine.
- **Warning** - Do not use any form of blasting media and/or surface conditioning discs when cleaning the intake manifold.

- **Valve Covers**

- Inspect the sealing surfaces of the valve covers for flatness and check for cracks at the flanges and bolt holes. If any cracks are found on the covers, they must be replaced. Do not try to repair them.
- Clean the covers and check for loose baffles at the fill holes and PCV outlets. Replace the cover(s) if they are defective.

- **Oil Pan**

- Inspect the oil pan rail for flatness. Check for cracking at the pan radius area and at the bolt holes. Check the front and rear oil pan seat rails for cracks or damage. If cracks are found replace the oil pan. Do not try to repair them.
- Inspect the oil drain plug for stripped threads or a loose weld nut. Do not try to repair cracks or a loose weld nut.

- **Front Cover and Lower End**

- Replace the crankshaft seal in the front cover. Do not use the old seal.
- Inspect the cover for cracks and heat checks, as well as inspecting the bolt holes for cracks. The blind holes will also need to be checked for cracks, as well as pulled threads and restricted depth. If any cracks are found, replace the cover.

- **Mechanical Fuel Pump**

- Clean the fuel pump and inspect the wear pad on the drive arm. Remember that mechanisms inside the pump wear. If the fuel pump has many miles on it or if excessive wear is present, replace it.

- **Flywheel / Flex Plate / Ring Gear**

- Check the flywheel for flatness using a dial indicator. Refer to the manufacturer's published information regarding exact specifications. Check for damaged teeth on the ring gear or flywheel. Replace if worn or damaged.
- Inspect the mounting holes and the torque converter or pressure plate mounting holes for cracks or wear. Inspect the clutch contact surfaces for heat cracking and discoloration. If cracks are found, replace the plate.
- **On manual transmission vehicles, the crankshaft pilot bearing must be transferred or replaced as required.**

GENERAL INSTALLATION PROCEDURES

TRANSFERABLE ENGINE COMPONENTS - cont.

- **Exhaust Manifold**
 - Inspect the manifold flanges for flatness and for carbon 'witness' marks, indicating a leak. If leaks are present or the exhaust manifold sealing surfaces are not flat, replace it with a new manifold.
 - Check the manifold for cracks, especially the external EGR connections, the exhaust pipe flanges, and the manifold mounting flanges. Compare the mounting hole spacing on individual runners to the new cylinder head for exhaust manifold shrinkage. If there is shrinkage, replace the manifold.
- **Pressure Plate / Release Bearing**
 - Inspect the clutch contact surface for heat checking or cracks. Check the release fingers for wear and even height.
 - Check the release bearing for facial wear and smooth rotation and the pressure plate for flatness.
- **Clutch Disc**
 - The clutch disc will need to be inspected for oil contamination and excessive wear, such as heat cracking of frictional material, worn frictional material, loose rivets and broken springs. If any of these conditions occur, replace the clutch disc.
- **Water Pump**
 - It is recommended to replace the water pump when installing a new engine. However, if the old pump is reused, check for cavitation erosion, impeller looseness, front seal leakage and smooth bearing feel. Replace the pump if it shows signs of wear.
- **Spark Plug Wires**
 - Thoroughly inspect the wires and boots for cracking, tearing, carbon tracking or other signs of damage. Suspect wires should be replaced.
- **Distributor (if applicable)**
 - Inspect the distributor for signs of oil contamination.
 - The drive gear should be checked for honed teeth. The shaft should rotate freely, with no side play, and the body and block seals should be free from distortion and cuts.
 - The cap/rotor should be free of corrosion, cracks and burrs. The distributor/oil pump drive should be free of nicks, burrs, and chipped teeth. If any of these conditions are present, replace the distributor.
- **Other Transferable Components**
 - Alternator (generator) and relative brackets
 - Air conditioning compressor
 - Power steering pump
 - Sensors
 - All pulleys and other bracketry

Ensure that all components are clean, all gasket material is removed, and they are free of wear and cracks. If any of these components can not be cleaned or repaired to good working order or are not within the manufacturer's specifications, replace them. Remember to be careful when cleaning aluminum components so that the sealing surfaces are not nicked or gouged.

When cleaning gasket sealing surfaces on new and remanufactured engines and/or cleaning parts from the failed engine to be reused, the use of surface conditioning discs that contain abrasives, such as aluminum oxide, may cause premature bearing failure.

THE USE OF SURFACE CONDITIONING DISCS IS STRICTLY FORBIDDEN.
(i.e., SCOTCH BRITETM, ROLO BRISTLE DISCSTM, Soc AttTM, ABRASIVE DISCS)

GENERAL INSTALLATION PROCEDURES

NON-TRANSFERABLE ENGINE COMPONENTS

Some components off the old engine will not be able to be used on the new replacement engine. This is because they will hinder the performance of the engine if they are not replaced. Or, they are part of routine maintenance and the opportunity to replace them should not be overlooked.

- **Oil Filters**
 - Oil Filters must always be replaced.
- **Thermostat**
 - The thermostat previously used in the original engine may be clogged or is worn out. The thermostat must be replaced prior to installing the new engine.
- **Oil Pump, Pick-up Tube and Screen**
 - These components come with the new engine.
- **PCV Valve and Crankcase Breather Filter**
 - These should be replaced to ensure that the emission standards of the engine are met and to prevent sludge, caused by gasses, and oil to build up in the crankcase.
- **Spark Plugs**
 - Be sure the new spark plugs are the proper heat range for the vehicle and engine application.
 - Failure to change the plugs or to get the proper heat range can cause the plugs to misfire, resulting in damage to the pistons through pre-ignition detonation.
 - Be sure the spark plug has the proper gap and seat for the vehicle application to avoid damage to the piston or blow-by damage.
- **Air Filters**
 - If the air filter is not replaced on a regular basis, the particles not being filtered can cause accelerated wear on the cylinder walls, piston rings and bearings
 - A dirty air filter can act as a choke and affect fuel consumption and engine performance.
- **Cooling System Sealing Tabs**
 - Necessary to Aid in sealing porosity and to clean silicates from the water pump shaft to prevent shaft seal damage.
- **Fuel Filter**
- **Engine Oil**
- **Antifreeze / Coolant**
- **Engine Oil Cooler (with every bearing failure)**

While the engine is apart and out of the vehicle, replace basic maintenance parts such as filters, hoses and belts.

- **Fuel Filters**
 - Used filters can become clogged, restricting fuel flow.
- **Hoses**
 - Hoses become brittle with age and may need to be replaced. Check the service manual for the vehicle application for proper hose replacement types and part numbers.
- **Belts**
 - Belts become brittle with age or glazed if they have been slipping. Check the service manual for the vehicle application for the proper belt replacement types and part numbers.

Take time to check the working condition of components such as the starter motor, cooling fan motor, battery and battery cables and fuel injectors. These components may need to be replaced in order for the new engine to function properly.

GENERAL INSTALLATION PROCEDURES

INSTALLATION PROCEDURES

Flush the Cooling System

A properly functioning cooling system is one of the most important items in installing an engine. It is important to rid the system of corrosion and other contaminants to ensure that the new engine has the proper heat transfer taking place. Otherwise, the engine will over heat and cause considerable damage. In addition to flushing the system, take time to verify the reliability and overall quality of the entire system, including the radiator and hoses. Flush the radiator thoroughly and check for blockages. Replace or inspect hoses and check for cracks, rips, brittleness and soft spots. By ensuring the entire cooling system is in proper working order, the chance of repeat engine failure is significantly reduced.

If the old engine is still running, flush the cooling system before removing the old engine. If the engine is not running, be sure to flush the cooling system immediately after replacing it with the new engine. Refer to the service manual for the specific instructions for flushing the cooling system for the vehicle.

After flushing the cooling system, add cooling system tabs (part number 1051687). Cooling system tabs aid in sealing porosity in aluminum and remove silicates from the water pump shaft that form from the coolant.

Installation

The following is an outline of the steps involved in installing an engine. They give a general overview of the order in which the transferable components from the old engine should be placed on the new engine. To begin, mount the engine on an engine stand with the oil pan facing upwards, intake valley facing downwards. Throughout the entire installation process, be sure to torque all bolts and other fasteners according to the manufacturer's specifications.

1. Install the oil pump and the oil pump shaft. **Fill the pump with GM E.O.S., part number 1052367, to aid in the initial suction and priming of the pump.** Do not use white lithium grease to pack the oil pump. This grease won't breakdown and will clog oil passages, which could cause engine oil starvation and seizing.
2. Install the new oil pick-up tube and screen and the crankshaft oil slinger. Be sure not to install the oil screen too close to the oil pan. Installing it too close can hinder the pick-up of oil causing oil starvation and seizing. Be sure to check the service manual for proper distance specifications.
3. Pour 1/4 of a can of GM E.O.S., part number 1052367, over the crankshaft, distributing it over the entire length of the crank.
4. Install the front cover using a front cover alignment tool. Apply gasket adhesive to the assembly to keep the gaskets in place during installation. Lubricate the front cover crankshaft seal with clean engine oil or E.O.S.
 - Be sure to seal the bolts that are entering the water jackets with RTV sealant.
 - Put the RTV sealant in the damper key slot to seal the key to the keyway.
5. Install the damper using the damper installation tool. Be sure to visually inspect the alignment before proceeding.
6. Install the water pump.
 - Be sure to coat the bolts that enter the water jackets with sealant.
 - Apply RTV sealant to the front cover and block joint.
7. Place the oil pan gasket on the block rail applying sealant at the mating corners. Be sure to properly align the oil pan, gasket and block. Be sure the drain plug is tight.

GENERAL INSTALLATION PROCEDURES

INSTALLATION PROCEDURES cont.

8. Rotate the engine on the engine stand so that the intake valley is facing up and the oil pan is facing down.
9. Pour the remainder of the E.O.S. over the rocker arm assemblies and camshaft.
10. **Pre-lube the engine with A.P.I. Starburst certified motor oil.** Pre-lubing the engine is necessary to avoid dry start damage. The most efficient way to pre-lube the engine is to use the **J-45299 engine pre-luber**. This will work on all applications. However, if no engine pre-luber is available and the engine has a mechanical distributor, the engine can be pre-lubed by priming the oil pump with a hand-held drill.

Using an oil pump priming tool or distributor shaft, rotate the oil pump with a drill at 200 to 500 RPM for two minutes after pressure builds up in the engine. This is to flush any debris from the engine without a load on the bearings while maximum clearances are present. Be sure to rotate the drill in the same direction as the distributor.

11. Install the intake manifold side gaskets and the end seals on the block and cylinder heads, placing RTV sealant on the corners.
12. Install the intake manifold, making sure to tighten the bolts in the proper sequence. Refer to the service manual for that vehicle and application for the specific sequence. Tighten the bolts from the inside out, alternating sides and criss-crossing front to back. If the intake manifold does not seal properly to the heads, water and other contaminants can enter the combustion chamber causing considerable damage.
13. Install the valve covers and be sure to tighten those fasteners in the proper sequence. The valve covers need to seal properly to avoid damage to the engine. Refer to the service manual for that vehicle and applications for the specific sequence and torque values.
14. Set the static ignition timing. Refer to the service manual for the proper procedure.
15. Install the exhaust manifold(s).
16. Install the fuel pump and fuel lines being sure of proper routing for the fuel lines.
17. Install the vacuum hoses. Check hoses for condition and replace as necessary.
18. Install the components listed below:
 - Front end bracketry
 - Crankshaft pulley
 - Water pump pulley
 - Air conditioning compressor
 - Air pump
 - Alternator (generator)
 - Power steering pump
 - All sensors that were removed from the original engine
 - Engine mounts (engine to frame)
 - External EGR components

GENERAL INSTALLATION PROCEDURES

INSTALLATION PROCEDURES cont.

19. Remove the engine from the engine stand.
20. Install the flywheel and clutch components.
21. Install the engine in the vehicle.

After Installation

Before the initial start up:

- Make sure the battery is fully charged.
- Make sure the engine has been pre-lubed, the oil is at its proper level, and the engine is pressurized completely.
- Check the transmission fluid, power steering fluid, brake fluid and coolant levels and condition. Change as necessary.
- Pressure check the cooling system, not exceeding 20 psi (138 kPa).
- Check hoses, cylinder head and freeze plugs.
- Check the radiator core, transmission oil cooler and the drain cock.
- Be sure the radiator cap maintains pressure and is the correct application.

Check the routing of the various other components, such as:

- Belts - check the tension and adjust them accordingly
- Electrical harnesses - check the ignition wiring and firing order, and the harnesses and wires to the alternator (generator), cooling fan, starter, sensors and the carburetor
- Intake system - check the ducts, filters and vacuum hoses for proper placement and condition
- PCV system - check the hoses and clamps for proper placement and condition
- Fuel lines - check for proper placement and condition
- Refer to the Vehicle Emissions Control information label for the proper hose routings.

After Initial Start-up Checklist

Check for fluid leaks in the following areas:

- The entire fuel system
- Valve / Camshaft cover gaskets
- Cylinder head gaskets
- Oil filter
- Oil level indicator
- Oil pressure sending unit
- Cup plugs or pipe plugs at the end of the oil passages
- Oil pan gaskets
- Oil pan front and rear end seals
- Crankshaft front and rear seals
- Side bolts

Note: If any leaks are found but the source of the leak is not detectable, use the 'black light and dye kit' or the 'pressure method' to pinpoint the source of the leak.

- GM engine oil fluorescent tracer dye, part number 12345795
- GM transmission fluorescent tracer dye, part number 12345796
- GM coolant system fluorescent tracer dye, part number 12345797

GENERAL INSTALLATION PROCEDURES

INSTALLATION PROCEDURES cont.

Check for fluid levels and conditions of the following:

- Engine Oil
 - Check for factory recommended pressure (see manual).
 - Verify oil level is at manufacturer's recommended amount.
- Engine Coolant
 - Make sure the thermostat is functioning properly.
 - Be sure the coolant is flowing freely through the system and that no blockages are present.

Check the following fluids for level, color and smell. Drain and flush before refilling, if necessary. Refer to service manual for further details.

- Transmission fluid
- Power steering fluid
- Brake fluid

Abnormal Noises

With engine running, listen for noises such as:

- Detonation
- Exhaust leaks
- Vacuum leaks
- Tapping / Knocking
- Loose or broken attaching components
- Drive belts

Dynamic ignition timing should be set at this time, if applicable. Incorrect timing is a common cause of engine failure. Be sure the vehicle's timing is correct. If unsure about specifications or procedures used in adjusting the timing and the idle speed, check the manufacturer's published information. Also, refer to the Vehicle Emission Control information label for specifications.

Check the engine vacuum. Install a vacuum gage at the intake manifold. The vacuum gage should read steady at approximately 18 in Hg at idle or above depending on the altitude. A low vacuum reading may indicate a restricted exhaust system, while a fluctuating vacuum may indicate internal engine concerns.

Other items:

- Cylinder heads, retorque if necessary
- Check belt tension, if applicable
- Check component routing

GENERAL INSTALLATION PROCEDURES

INSTALLATION PROCEDURES cont.

Engine Break-In

Once the engine has been successfully installed and the oil pump has been primed, start the engine and let it idle at 1600 to 2000 RPM for 10 to 20 minutes allowing the oil pressure and temperature to stabilize. Refer to the service manual for the proper pressure range. During this time, where applicable, adjust the timing and valve clearance and check for leaks.

Road test the vehicle for a minimum of 10 miles (16.09 km) with combined city and highway driving. Do not exceed 50 miles per hour (80 kph) or use any fast throttle responses.

Instruct the customer that the first service interval for changing oil and the oil filter should be between 300 and 500 miles (500 km and 800 km). For subsequent service, refer to the manufacturer's recommended intervals.

GENERAL ENGINE DIAGNOSTICS

Proper diagnosis of a failed engine is critical. Otherwise, the same failure cause will affect the performance and reliability of the best replacement engine. As such, verifying proper operation of the various engine systems is mandatory to avoid another failure that may not be covered under warranty. If the cause of failure was inadequate or improper maintenance, the owner should be informed that recommended schedules must be followed on the replacement.

CAUSES OF ENGINE FAILURE

Engines rely on a number of related systems for their operation, performance and durability. The related systems include:

- Starting and Charging
- Ignition
- Fuel
- Valve Train
- Lubrication
- Cooling
- Emission Controls
- Engine Controls

Various problems in any one of these systems can degrade engine performance and prevent the engine from operating at all. In most cases, specific trouble symptoms will become evident before the engine suffers a catastrophic failure or serious internal damage to require its replacement. On newer vehicles, electronic engine controls and On Board Diagnostics (OBDII) are able to identify potential problems requiring service before a symptom is noticed.

While many factors can impact engine performance and driveability, the most common causes of engine failure include the following:

- Insufficient Lubrication
- Oil Contamination
- Poor Coolant Circulation
- Pre-Ignition or Detonation

Usually the reason an engine failed is apparent. Insufficient lubrication may have caused serious wear and seizure of internal engine parts. Oil contamination may have caused premature failure of bearings or other components. Poor coolant circulation may have caused overheating which ruptured gaskets or caused the engine to seize. Pre-ignition or detonation in the combustion chambers may have caused piston and valve damage, or ruined the cylinder block and head.

You will usually know why a replacement engine is needed, but identifying what led to the reason for failure is more important.

GENERAL ENGINE DIAGNOSTICS

DIAGNOSING AN ENGINE FAILURE

Preliminary Checks

Several preliminary checks are recommended when a customer arrives with a serious engine operating concern:

1. Understand the specific customer concern and the problem symptoms.
2. Verify the concern under the same conditions that it occurred.
3. Perform a visual/physical inspection for the following symptoms or signs of engine failure causes:
 - Serious oil or coolant leaks which may indicate engine block cracks or cylinder head gasket failure.
 - Engine noises that may indicate internal engine problems other than timing or fuel system defects.
 - Overheating caused by inadequate cooling from a plugged radiator, stuck thermostat or collapsed coolant hoses.
 - Excessive wear caused by a lack of lubrication from using an incorrect oil, inadequate oil changes, a too-low oil level, or a plugged filter, PCV valve or EGR valve.
 - Incorrect timing causing overheating or performance problems.
 - Unusual odors in the engine compartment, which may indicate excessive oil consumption, coolant hose/water pump failure, melted wiring or ruptured/melted seals or gaskets.
 - Obvious exhaust emissions, with odor and colors, which may indicate combustion problems.
 - Electrical failures from disconnected connectors or broken or melted wires.
 - Engine performance problems from kinked, split or missing vacuum hoses.
 - Hard starting, rough idling from collapsed or damaged air intake components.
 - Electrical or mechanical malfunctions caused by improper installation of non-factory accessory items.
4. Never overlook the possibility that poor engine performance, even an inoperable condition, may be caused by problems in other systems - starting/charging, ignition, fuel, intake and exhaust, lubrication, cooling, emission controls and engine controls.
 - A weak battery, defective starter motor or failed generator will prevent proper engine start-up and may damage components.
 - Incorrect ignition timing settings, as well as various defective ignition components, can easily shut down engine operations.
 - Fuel system problems, such as blockage, contamination and defective/incorrect parts can cause serious engine concerns.
 - Defective intake and exhaust systems can affect combustion quality and lead to detonation problems.
 - Contaminated lubrication and cooling systems can lead to catastrophic engine failure.
 - Insufficient engine cooling can lead to severe parts damage and even seizure from overheating.
 - Emission-control settings and defective components may affect engine operation or cause serious problem symptoms.
 - Electronic-control system components provide essential engine operating data to the PCM and must be checked with a scan tool or specific DTCs.

GENERAL ENGINE DIAGNOSTICS

Insufficient Lubrication Diagnosis

Proper lubrication is critical for engine life. Engine parts are exposed to extremely high temperatures, pressures and mechanical friction. Without sufficient lubrication, these parts can quickly fail from abnormal wear, deep scoring and complete seizure involving metal welding.

All engines have a recommended lubricant or oil type, certified by the American Petroleum Institute (API). A Starburst certified oil is the recommended oil for vehicles. Containers for this oil have a "starburst" certification mark that makes it easier to select engine oils that meet performance standards set by international vehicle makers. Containers of Starburst certified oil also have the standard API "donut" certification mark, which identifies the viscosity, API performance category and energy conservation characteristics. Using the incorrect oil can lead to insufficient lubrication.

Engines also have a recommended oil capacity and change interval. Insufficient lubrication occurs when the oil level is below the minimum recommended level because of leakage or burn-off, or when the oil flow through the engine lubrication passages is blocked because of mechanical problems or sludge formation. The oil filter should be changed at the same time as the oil.

If an engine failure is caused by lack of lubrication, check for leakage from external components. Flush an external oil cooler and lines; ***replace the cooler if a catastrophic engine failure occurred.*** Make sure that the correct viscosity oil was used and that the oil filter and PCV valves were properly installed. Also, check the engine itself. Compression-set manifold gaskets, worn valve guides or piston rings can lead to excessive oil use.

Oil Contamination Diagnosis

Contamination is one of the worst enemies of engine lubrication. Any foreign materials entering the crankcase, as well as wear materials from inside the engine itself, can wear the cylinder walls and pistons/rings, bearings, shafts, timing components, oil pump parts and valve train components. Oil contamination is one of the most common causes of bearing failure.

Usually, engine failures caused by oil contamination are relatively easy to diagnose because component failures, restricted oil flow, or a lack of maintenance have caused the very obvious lubrication system problems. The lubricating oil can also be degraded by coolant contamination from a cracked cylinder block or head. Or, the oil can be diluted and have reduced lubricating capabilities by mixing with unburned fuel that washes past worn piston rings. The oil may have also been contaminated by improper repair procedures that introduced dirt, abrasives or other foreign materials.

- If the oil drained from the failed engine contains metallic particles, sludge, sediment, or varnish remnants, the cause or causes should be determined. Check the following:
 - If the engine oil had not been regularly changed at recommended intervals, the engine may have had a serious deposit build-up that was flushed into the oil upon failure.
 - If an incorrect engine oil (not API-certified) was used or the oil was not regularly changed according to operating conditions, heavy sludge deposits and sediment should be expected.
- If the oil is diluted with coolant or fuel, check the following:
 - Oil diluted with Coolant: An oil cooler failure, casting crack or gasket leak may be indicated.
 - Oil diluted with Fuel: A too-rich fuel mixture, leaking fuel injector, defective ignition system, or severely worn rings may be indicated.

Warranty analysis shows that the use of abrasive surface-conditioning discs, sandpaper or grinders to remove gasket residue during engine service is one of the leading causes of bearing failure. The following abrasive disc products should NEVER be used on these high-quality new and remanufactured engines:

- ScotchBrite™ abrasive discs
- Rolo Bristle Discs™ abrasive discs
- Soc Att™ abrasive discs

The only method of gasket removal approved by GM Goodwrench is using a hand scrapper.

GENERAL ENGINE DIAGNOSTICS

Poor Coolant Circulation Diagnosis

Proper engine operation depends on coolant to flow through the engine water jackets and absorb the heat of combustion, and then to transfer it to the outside air by flowing through the radiator. A typical engine (coolant) operating temperature is about 200°F (94°C); some older engines run cooler and some newer engines run hotter.

With proper flow, the engine coolant in most vehicles can readily absorb, transfer and release heat. When the flow or volume of coolant is too low, engine temperatures may rise beyond design specifications. The engine may seize as various parts burn off lubrication and expand. Engine failures caused by overheating from poor coolant circulation are common.

The most common cause of engine overheating is poor coolant circulation. **If the cause of the overheating problem is not corrected, a replacement engine will also fail.** The following checks must be performed:

- *Coolant Type and Level* - Coolant types and levels are specified for most engines.
- *System Blockage* - Various conditions may partially block cooling system passages and prevent adequate coolant flow. Some of these conditions include sediment and scale build-up in the radiator or the heater core, or sludge build-up in the engine water jackets or coolant passages. The radiator and heater core must be flushed and clean to insure that sediment will not enter the new engine or possibly limit coolant flow again. A thermostat stuck closed must also be replaced. GM Parts recommends always replacing the thermostat whenever a replacement engine is installed.
- *System Leakage* - Loose clamps on hoses, deteriorated hoses, radiator core or heater core pinhole leaks, a defective radiator drain cock, a failed water pump and internal engine cracks and gasket failures are all problems that can cause a loss of coolant.
- *Gasket Failure* - A defective or failed head gasket may allow exhaust gas to leak into the cooling system. These gases will form strong acids when combined with the coolant, and lead to serious radiator corrosion and damage other parts. Combustion leaks in the valve areas can cause cracked valve seats and cylinder heads. The leaking gases force coolant away from the leak area during heavy acceleration. The area overheats and can crack when acceleration stops and the coolant rushes back to the leak area.
- *Rust* - Rust formation in the cooling system can also prevent proper coolant flow and lead to engine overheating. This is most often caused by operating the vehicle for extended periods of time with a low coolant level. Especially systems with long-life coolants such as DEX-Cool are not immune to this problem. The low coolant level, not the coolant itself, is at fault for rust formation. To correct the problem, the entire cooling system may require extensive flushing. Refer to GM Bulletin 99-06-02-012B.

Only use distilled water to mix with new coolant. Never add tap water.

GENERAL ENGINE DIAGNOSTICS

Pre-Ignition or Detonation Diagnosis

With normal engine operation, the combustion process is smooth from beginning to end, as the air-fuel mixture is compressed and burned evenly for maximum power. Today's internal combustion engines operate on a basic four-stroke cycle:

- **Intake:** The camshaft opens the intake valve and the air-fuel mixture enters the cylinder as the piston moves to its lowest point, Bottom Dead Center (BDC).
- **Compression:** The intake valve closes and the piston moves to Top Dead Center (TDC). The air-fuel mixture is compressed to about one-eighth or ninth of its original volume.
- **Power:** The spark plug fires, igniting the compressed air-fuel mix. This releases a tremendous amount of energy against the piston, pushing it back to BDC. This power is transferred to the crankshaft.
- **Exhaust:** The camshaft opens the exhaust valve as the piston moves back to TDC and forces out burned gases. The exhaust valve then closes and the intake valve opens to begin the cycle again.

With the correct air-fuel mixture and proper valve and spark timing, the basic four-stroke cycle takes place in each engine cylinder according to a certain sequence. Maximum power is generated at a smooth power flow results in optimum engine performance. The long-term effects of using incorrect air-fuel mixtures and/or incorrect valve or ignition timing may cause pre-ignition, detonation or run-on.

Pre-ignition occurs when the air-fuel mixture ignites too early, usually before the compression stroke is completed. *Detonation* occurs when the air-fuel mixture burns unevenly and the end gases explode violently near the end of the power stroke. *Run-on* occurs when "hot spots" (carbon deposits from an incompletely burned rich mixture) ignite the air-fuel mixture without a spark, causing combustion with the ignition off.

The common owner concern is engine "knocking". Uncorrected, the damage can be significant and require an engine replacement. Such damage can include cracked pistons, damaged rings, blown head gaskets and even cracked heads if the detonation is severe enough. Depending on the cause, the air-fuel ratio may require adjustment, incorrect timing reset to specifications or carbon deposits removed using an engine cleaner.

If the engine failure has been caused by pre-ignition or detonation damage, the fuel, ignition and emission-control systems must be thoroughly checked for the cause of the problem. On newer vehicles, Diagnostic Trouble Codes (DTCs) may be set and indicate where system repairs are needed. Replacing an engine without correcting the failure cause will lead to another failure.

- **Fuel System** - Check the air induction system as well as the fuel bending and metering devices. Both a too-rich air-fuel mixture as well as a too-lean mixture can cause pre-ignition or detonation. An incorrect mixture may also create carbon deposits because of an inefficient combustion process.
- **Ignition System** - Check all of the devices that control the ignition timing. Usually, timing that is too advanced may cause pre-ignition or detonation. If the vehicle has a distributor, check the cam lobes and bushings, as well as the mechanical/vacuum advance mechanisms. Also, check the harmonic balancer for mislocation of the outer ring, or for poor condition of the rubber between the inner and outer rings. Check the camshaft and crankshaft sensors on vehicles without distributors. A failed knock sensor or defective ignition module can also cause an extremely advanced spark timing. The ECM reads sensor input to run timing as advanced as possible without causing knock. Problems with valve train timing should also be considered.
- **Emission Controls** - Typical emission-control components that can cause pre-ignition with a too-lean air-fuel mixture include the EGR valve, MAP or MAF sensors, TPS and IAC valve. Check the engine control module as well. Typical components that could cause a too-rich mixture (and create carbon deposits) included ECT sensor, IAC valve, MAP or MAF sensors, EVAP, O2S and PCV. Normally, checking these emission-control components must be done with a scan tool after the replacement engine is installed. If the engine still runs, check these devices prior to replacing the engine.

GENERAL ENGINE DIAGNOSTICS

ENGINE TESTING

A variety of procedures are used to check engine performance and identify causes of operating concerns. With the electronic engine controls and On Board Diagnostics used on today's vehicles, the approach to troubleshooting has changed considerably.

Manifold Vacuum Check

Manifold vacuum tests can provide an excellent indication of overall engine condition. Problems with manifold and combustion chamber sealing, valve action and condition, ignition timing, the air-fuel mixture, PCV operation and exhaust restrictions can be identified.

Vacuum gauge readings will be affected by variations in atmospheric pressure (altitude, weather, etc.). However, the action of the gauge needle is more important than the specific vacuum reading. Vacuum gauge readings can indicate a number of engine operating problems. General procedures include:

1. Connect a tachometer into the engine (ignition system).
2. Connect a vacuum gauge to an intake manifold port.
3. Start and run engine until it reaches normal temperature.
4. Run the engine at idle, low cruise and high cruise.
5. Note the vacuum readings and any fluctuations at each speed.
 - Normal readings should be 15 - 22in. HG with the needle steady, indicating good combustion chamber sealing.
 - A steady low reading indicates late ignition valve timing, low compression or vacuum leaks.
 - A fluctuating reading indicates uneven compression, incorrect air-fuel ratios, uneven timing, misfiring plug, or vacuum leaks.
 - Readings that drop irregularly at idle indicate sticking valves.
 - Readings higher than normal at idle indicate incorrect timing.
 - A reading that does not increase when the throttle closes from high cruise may indicate worn rings, cylinders or valves.
 - A reading that drops at high cruise, but does not increase when the throttle closes, may indicate a restricted exhaust system.

These vacuum tests do not isolate a worn cylinder or distinguish between late ignition timing or valve timing. However, the results can lead to more detailed testing of indicated problems.

GENERAL ENGINE DIAGNOSTICS

Engine Compression Check

An engine compression check measures the ability of the cylinders to hold compression. If cylinder compression leaks, power is lost. Using a gauge, compression readings are taken for each engine cylinder and compared with specifications. A typical gauge will have an adapter that either screws or plugs into the spark plug (glow plug) holes. For gasoline engines, it should be able to read up to 250psi (1722kPa). For diesel engines, it should read up to 800psi (5512kPa).

Use the following procedures for an engine compression test:

1. Preliminary test preparations include making sure that:
 - The battery is fully charged.
 - The correct type of oil has been used.
 - The oil level is correct for the crankcase capacity.
 - A remote starter is connected, if needed.
2. Disable the ignition (or diesel injection system).
3. Remove the spark plugs (glow plugs); use compressed air to clean the area around the plugs before removing them.
4. Block the throttle plate wide open (allowing air into the engine and preventing engine flooding that would reduce cylinder lubrication).
5. For a "dry" compression test:
 - With the compression gauge on 'zero', crank the engine through four compression strokes.
 - Record the compression reading.
 - Repeat the check and record the readings for each cylinder.
 - If some cylinders have low compression, test "wet".
6. For a "wet" compression test:
 - Inject about 15ml (1 tbs.) of oil into each cylinder through the plug hole.
 - Crank the engine through four compression strokes.
 - Check each cylinder that previously read low.
 - Record the compression readings.

Notice: A "wet" compression test will not be valid on engines with horizontal pistons. The oil will not flow evenly around the pistons.

Specifications may list a minimum pressure and an allowable variation between cylinders. Depending on the engine, some recommend no more than a 20psi variation between cylinders. Others recommend that the compression in any one cylinder should not be less than 75-percent of the highest cylinder. Generally, even if a specification is not listed, serious internal wear or sticking rings are indicated if compression is below 100psi.

Guidelines for interpreting the results of compression testing include the following:

- *Normal* - Compression builds up quickly and evenly to specified levels in each cylinder. All cylinders should be within 20 percent of each other.
- *Piston Rings Leaking* - Compression is low on the first stroke and tends to build up on the following strokes, but does not reach normal. Readings improve considerably with the addition of oil. The piston rings are most likely leaking.
- *Valves Leaking* - Compression is low in the first stroke and does not tend to build up on the following strokes. Does not improve much with the addition of oil. The valves are most likely leaking.
- *Leaking Gasket* - Two adjacent cylinders have lower-than-normal compression, and injecting oil into these cylinders does not increase compression. The head gasket between the two cylinders is most likely leaking.

Important: If the results of the Engine Compression Test are not conclusive (the cause of low compression), perform a Cylinder Leakage Test.

GENERAL ENGINE DIAGNOSTICS

Cylinder Leakage Test

A cylinder leakage test also checks compression, but in a different way. A special leakage tester, which may or may not be built into an engine analyzer, applies shop air pressure to a cylinder with the piston at TDC on the compression stroke. With the piston at TDC, both valves are closed and very little air should escape except for a small amount past the piston ring gaps. The tester pressure gauge shows leakage as a percent of cylinder compression. While specifications vary, any reading above 20-percent would indicate excessive leakage. Specific results can pinpoint the source of compression leakage.

Follow the specific tester instructions and use the following procedures to perform a cylinder leakage test:

1. With the engine at operating temperature, disable the ignition (or diesel injection system).
2. Remove the spark plugs (glow plugs), air cleaner and oil dipstick or filler cap.
3. Block the throttle wide open.
4. Disconnect the PCV hose from the crankcase.
5. Remove the radiator cap; add coolant, if needed.
6. Rotate the crankshaft (or crank the engine) until the piston for the cylinder being checked is at TDC.
7. Apply air pressure to the cylinder and read the tester gauge.
 - Less than 10% = good compression
 - 10% to 20% = fair compression
 - 20% to 30% = poor compression
 - More than 30% = serious problem
8. If the cylinder leakage is more than 20-percent, listen for air leaking from the following sources:
 - Air escaping from the crankcase or oil filter/dipstick indicates worn/broken rings, a cracked piston or worn cylinder walls.
 - Air escaping from the intake indicates a worn intake valve.
 - Air escaping from the tailpipe indicates a worn exhaust valve.
 - Air bubbles in the coolant indicate a blown head gasket or a cracked head or block.
 - Air blowing from an adjacent spark plug (glow plug) hole indicates a leaking head gasket or a casting crack between the two cylinders.

Repeat these test procedures for each of the cylinders. The leakage tester reading should not vary more than 10-percent between all of the cylinders.

GENERAL ENGINE DIAGNOSTICS

Camshaft Gear Timing Check

If engine tests did not reveal serious engine damage, use the following procedures to check for proper camshaft gear timing:

1. Remove or disconnect all of the spark plugs (glow plugs).
2. Remove the valve cover and rocker arms for the #1 cylinder.
3. Mount a dial indicator on the exhaust pushrod (or top of valve retainer for OHC) to read the camshaft exhaust lobe lift.
4. Rotate the crankshaft slowly clockwise (CW), until the dial indicator shows maximum exhaust lobe lift.
5. Place a chalk mark on the harmonic balancer (torsional damper) next to the timing tab.
6. Remove the dial indicator from the exhaust pushrod and reposition it on the intake pushrod.
7. Rotate the crankshaft slowly clockwise (CW), until the dial indicator shows maximum intake lobe lift.
8. Place a second mark on the harmonic balancer, again next to the timing tab.
9. Measure the distance of each chalk mark to the factory-set camshaft gear-timing groove (TDC) in the harmonic balancer.
 - If the distance of each chalk mark to the factory groove for TDC is roughly the same, the camshaft timing gear is properly indexed (positioned) to the crankshaft gear.
 - If the distance of each chalk mark to the factory groove is not the same, differing by an inch or more, the camshaft timing gear is not properly indexed to the crankshaft gear by at least one tooth or more.

Besides camshaft gear timing, setting ignition timing to specifications is also important for proper engine operation. If a catastrophic engine failure did not occur and if engine tests indicated that replacement is not necessary, correcting the timing may resolve a customer concern.

GENERAL ENGINE DIAGNOSTICS

Engine Mechanical Diagnosis

Diagnosing various engine mechanical concerns involves starting with the owner concern (problem symptom), understanding that several possible causes may contribute to that symptom. Also, using certain checks or tests to eliminate some causes and to find the root cause.

Concern	Possible Cause	Check or Test
Engine will not turn over	<ul style="list-style-type: none"> Electrical failure (battery, starter, solenoid) Hydrostatic lock Seized engine 	<ul style="list-style-type: none"> Turn engine over by hand to verify that this is not a mechanical failure. Determine fluid (coolant, oil, water) source. Remove plugs, suction out cylinders. Pressure test cooling system with plugs out. Determine damage and/or repair cause. Look for external causes, such as accessories. Turn with breaker bar to verify mechanical failure.
Engine cranks, will not start	<ul style="list-style-type: none"> Restricted exhaust system Fuel, ignition system problems Low compression 	<ul style="list-style-type: none"> Remove intermediate exhaust pipe before catalytic converter. First test cranking vacuum; locate restriction. Check for proper fuel pressure, injector pulse, spark. Stuck or burned valves, pistons/rings; head gasket; valve timing. Perform compression test, check oil viscosity.
Rough Idle	<ul style="list-style-type: none"> Fuel, ignition or emission-control system problems Uneven cylinder compression Bent pushrod/broken valve spring Faulty engine mount 	<ul style="list-style-type: none"> Check/test engine vacuum, ignition firing patterns (scope), and EGR function. Perform compression test (wet and dry). Repair, identify cause and residual damage. Load engine with brake applied, shift D-R-D as mounts are checked. Replace as needed.
Smoke	<ul style="list-style-type: none"> White - Water vapor Blue - Oil burning Black - Poor combustion (excess fuel) 	<ul style="list-style-type: none"> Determine if normal or cooling system problem. Pressure test cooling system both cold and hot. See checks for excessive oil loss. Check air-fuel ratio for too-rich mixture. Use exhaust gas analyzer to check for HCs.
Excessive oil loss	<ul style="list-style-type: none"> Continuous WOT driving, severe engine service (towing, load) External oil leaks Improper oil viscosity Defective PCV system Worn valve guides or seats Worn piston rings 	<ul style="list-style-type: none"> Check with owner; higher-than-normal oil consumption may be due to operating habits. Inspect, perform dye/black light check as needed. Change oil to specified; check consumption. Test vacuum; make sure baffles have not been removed. Check for blue smoke upon start-up. May require service or replacement; disassembly/inspection. Perform compression test; much higher wet compression test results typically indicate worn piston rings.

GENERAL ENGINE DIAGNOSTICS

Engine Mechanical Diagnosis *cont.*

Concern	Possible Cause	Check or Test
Low oil pressure	<ul style="list-style-type: none"> — Loose or plugged oil pick-up screen — Faulty pressure switch or sensor — Defective oil pressure gauge — Incorrect oil viscosity — Diluted oil — Worn oil pump — Plugged oil filter — Excessive bearing clearances, spun bearing, contaminates 	<ul style="list-style-type: none"> — Perform visual inspection, service or replace as required, identify any other damage. — Test oil pressure. Replace switch/sensor. — Check with known good gauge. — Change oil to specified; check pressure. — Change oil. Inspect for contaminants (water, dirt, fuel, etc.) — Check pump; replace as needed. — Change oil; check for contaminants. Test bypass valve. Check lubrication system pressure, engine operating. — Check oil viscosity. Also check for contamination from surface-conditioning discs or rotary buffers.
Overheating	<ul style="list-style-type: none"> — Coolant circulation inadequate — Coolant level too low — Internal blockage or cracks — Airflow across radiator inadequate — Head gasket(s) ruptured 	<ul style="list-style-type: none"> — Check for defective water pump, thermostat sticking closed, low coolant level. — Check boil-over history (owner input), external/internal leakage with underhood steam, exhaust white smoke. — Flush cooling system; check for leaks/exhaust vapor. — Check for damaged cooling fins in radiator/AC condenser; also, blockage in airflow path, damaged air dam. — Check for air bubbles in radiator coolant; test for exhaust gases in coolant.

GENERAL ENGINE DIAGNOSTICS

Engine Noise Diagnosis

Engine noises, like various symptoms of engine mechanical problems, can provide direction for specific checks and further testing.

Noise	Symptom Description	Check or Test
Double knock	Light crankshaft-speed knocking noise heard for the first few minutes after start-up.	Check for a loose piston pin.
Rattling	<ul style="list-style-type: none"> — Light, irregular, "dieseling" or "marbley" rattle, ticking noise heard for first few minutes of start-up. — Light, regular, camshaft-speed ticking noise, heard best when the engine is increased to 2000 rpm, then released to idle 	<ul style="list-style-type: none"> — Check for several loose piston pins. — Check for defective/misaligned balance shaft bearing.
Thumping	Light, regular thumping noise heard best near accessory drive belt pulleys.	Check drive belt pulley tensioner. Adjust to specified deflection. Check pulley alignment.
Dull Knock	Heavy, regular, dull metallic knock that occurs on acceleration, under load.	Check for incorrect main bearing clearances.
Chirping, Squealing	Steady "chirping" at nominal speeds, loud squealing upon acceleration or tight turns.	Check drive belts for looseness/glazing; check pulleys/tensioner; check for paint in grooves.
General Knock	Includes dull, regular and metallic knocking.	Check for incorrect connecting rod bearing clearances, piston scuffing, tight piston pin, clogged anti-drainback filter.
Sharp Knock	Light, regular, sharp metallic rapping of clattering knock heard best at speeds between 25 and 35 mph.	Check for loose flexplate bolts, cracked flexplate, incorrect connecting rod bearing clearances. Repair as required.
Loud pop	GM Northstar - Pop when key is released after extended crank and failure to start.	May be a normal pressure release from the fuel induction system/intake manifold. Refer to GM Bulletin 57-60-02.
Valve train noise	<ul style="list-style-type: none"> — Worn or defective camshaft may be problem. — Loose rocker arm attachments — Worn rocker arm or pushrod — Broken valve springs — Sticking Valves — Worn, dirty, defective lifters — Defective fuel pump, pushrods — Low oil pressure — Worn valve guides — Collapsed Lifters 	<ul style="list-style-type: none"> — Check for popping noise through throttle body; perform visual inspection; check with dial indicator. — Visual inspection; service as required. — Diagnosis cause and repair. — Visual inspection; vacuum gauge test. — Visual inspection; vacuum gauge test. — Visual inspection. — Visual inspection. — Check oil pressure; repair as needed. — Perform vacuum test; use dial indicator to check wear. — Oil drained out of lifters, replace as indicated.

GENERAL ENGINE DIAGNOSTICS

Engine Noise Diagnosis *cont.*

Noise	Symptom Description	Check or Test
Tick	<ul style="list-style-type: none"> GM C/K vehicles - On cold start at low temperatures during engine deceleration after idle flare. Not consistently repeatable. 	<ul style="list-style-type: none"> Confirm proper VCM calibration. Refer to GM Bulletin 99-06-04-014 for details.
Knock, engine cold. Continues for 2 to 3 minutes. Increases with torque.	<ul style="list-style-type: none"> Flywheel may be contacting splash shield. Loose or broken torsional damper or drive pulleys. Excessive piston-to-bore clearance (piston slap). Bent connecting rod. 	<ul style="list-style-type: none"> Perform visual inspection. Remove accessory belts; perform visual inspection. Check with bore gauge and T-gauge micrometer. Perform visual inspection.
Heavy knock, engine hot, torque applied.	<ul style="list-style-type: none"> Broken harmonic balancer or pulley hub. Loose torque converter bolts. Exhaust system grounding out. Cracked flywheel, loose rivets. Incorrect main bearing or rod bearing clearance. 	<ul style="list-style-type: none"> Remove drive belts; perform visual inspection, service or replace as required. Visual inspection. Visual inspection; carbon knock possible. Visual inspection. Visual inspection.
Light knock, engine hot, under light load conditions.	<ul style="list-style-type: none"> Pre-ignition; ignition control problems; detonation. Poor fuel quality Loose torque converter bolts. Exhaust leak at manifold. Excessive rod bearing clearance. 	<ul style="list-style-type: none"> Check engine codes and ignition timing settings; reset to specifications; check EGR for blockage. Owner input; use known good fuel. Visual inspection. Visual inspection. Visual inspection
Start-up knock, lasts a few seconds.	<ul style="list-style-type: none"> Timing chain tensioner not properly set. Improper oil viscosity. Bearing knock. Hydraulic lifter bleed down. 	<ul style="list-style-type: none"> Check filter with anti-drainback valve. Change oil; check engine performance for knock. Confirm that filter has anti-drainback valve. Check requires special equipment.
Knock at idle, engine hot.	<ul style="list-style-type: none"> Drive belts too tight; accessory belt pulley bearing loaded. Improper oil viscosity. Noisy piston pin (double knock). Loose torsional damper. 	<ul style="list-style-type: none"> Remove accessory belts; observe change, if any. Change oil; check engine performance for knock. Short out suspect cylinder; noise should disappear. Perform visual inspection with engine under load.

4-Cylinder Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12363193

133 CID New

2.2L

1990-91 Chevrolet J, L (LM3)(2.2G)

Engine-Specific Content: Crankshaft Balancer, Front Cover, Oil Pan, and Spark Plugs**Notes:** Does not contain Flywheel, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.**Replaces:** 12363161**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12363194

133 CID New

2.2L1992-93 Chevrolet J, L (LN2)(2.2-4)
1993 Oldsmobile, Buick A (LN2)(2.2-4)**Engine-Specific Content:** Crankshaft Balancer, Front Cover, Oil Pan, and Spark Plugs**Notes:** Does not contain Flywheel, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.**Replaces:** 12363160**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12363195

133 CID New

2.2L1994-95 Oldsmobile, Buick A (LN2)(2.2-4)
1994-95 Chevrolet L (LN2)(2.2-4)
1994 Chevrolet J (LN2)(2.2-4)
1995 Chevrolet, Pontiac J (LN2)(2.2-4)**Engine-Specific Content:** Crankshaft Balancer, Front Cover, Oil Pan, Spark Plugs, and Oil Filter**Notes:** Does not contain Flywheel, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.**Replaces:** 12363158**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12465411 133 CID Reman **2.2L**

1994-95 Chevrolet, GMC S1 (LN2)(2.2-4)
1994-95 GMC Z1 (LN2)(2.2-4)

Engine-Specific Content: Front Cover, Oil Pan, and Oil Filter

Notes: Does not contain Flywheel, Crankcase Vent Sys, Thermostat, Intake or Exhaust Manifold, Crankshaft Posn, Knock, Map, Cool Temp or Oil Level Sensors.

Replaces: 12363159, 12363198

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12465434 134 CID Reman **2.2L**

1996 Chevrolet, GMC S1 (03-53)(LN2)(2.2-4)

Engine-Specific Content: Front Cover and Oil Pan

Notes: Does not contain Flywheel, Crankcase Vent Sys, Thermostat, Intake or Exhaust Manifold, Crankshaft Posn, Knock, Map, Cool Temp or Oil Level Sensors.

Replaces: 12360470, 12363199

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12465435 134 CID Reman **2.2L**

1997 Chevrolet, GMC S1 (LN2)(03-53)

Engine-Specific Content: Crankshaft Pulley, Oil Pan, Front Cover, and Spark Plugs

Notes: Does not contain Flywheel, Crankcase Vent Sys, Thermostat, Intake or Exhaust Manifold, Crankshaft Posn, Knock, Map, Cool Temp or Oil Level Sensors.

Replaces: 12363176, 12363200

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12465447 134 CID New **2.2L**

1998 Chevrolet, GMC S1 (LN2)(2.2-4)(03-53) MFI

Engine-Specific Content: Crankshaft Pulley, Oil Pan, Front Cover, Spark Plugs, and Valve Covers

Notes: Does not contain Flywheel, Crankcase Vent Sys, Thermostat, Intake or Exhaust Manifold, Crankshaft Posn, Knock, Map, Cool Temp or Oil Level Sensors.

Replaces: 88894190, 88890516, 12482042

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12593224

134 CID New

2.2L

2002-05	Chevrolet, Pontiac	J (L61)(2.2-4) MFI
2002-04	Oldsmobile	N (L61)
2002-05	Pontiac	N (L61)
2004-05	Chevrolet	N (L61)

Engine-Specific Content: Oil Pan, Front Cover, and Valve Cover

Replaces: 12574621, 12586529

Replaced By:

Notes: If using on vehicle with manual transmission, transfer flywheel from existing engine. For 2003 MY, fuel rail/injectors must be changed to 2003 content.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12593292

134 CID New

2.2L

2004	Chevrolet	3Z (L61)
2005	Chevrolet	3A (L61)

Engine-Specific Content: Oil Pan and Front Cover

Replaces: 12587403

Replaced By:

Notes: If using on vehicle with manual transmission, transfer flywheel from existing engine.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894187

134 CID New

2.2L

1999-2002	Chevrolet, Pontiac	J (LN2)(2.2-4) MFI
-----------	--------------------	--------------------

Engine-Specific Content: Front Cover, Spark Plugs, and Valve Cover

Replaces: 88890515, 12482041

Replaced By: 88984243

INSTALLATION INSTRUCTIONS

Installation instructions are included with the engine.

88894189

134 CID New

2.2L

1998	Chevrolet, Pontiac	J (LN2)(2.2-4) MFI
------	--------------------	--------------------

Engine-Specific Content: Oil Pan, Front Cover, Spark Plugs, and Valve Covers

Replaces: 88890514, 12482040

Replaced By: 12465446

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88984244

134 CID New

2.2L

1999-2000	Chevrolet, GMC	S1 (LN2)
2000	Chevrolet, GMC	S1 (L43)
2001-02	Chevrolet, GMC	S1 (L43) MW2, M30, NC1, NF4, NF7
2003	Chevrolet, GMC	S1 (LN2) M30, MW2

Engine-Specific Content: Front Cover, Spark Plugs, and Valve Covers

Replaces: 88894188, 88890517, 12482367, 12482043
Replaced By: 12465447

Notes: Exhaust manifold may need to be changed for applications with A.I.R.

INSTALLATION INSTRUCTIONS

Installation instructions are included with the engine.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360619

138 CID Reman

2.3L

1989-90	Pontiac, Oldsmobile	N (LG0)(2.3A)
1990	Chevrolet	L (LG0)(2.3A)
1990	Oldsmobile	W (LG0)(2.3A)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360620

138 CID Reman

2.3L

1991	Chevrolet	L (LG0)(2.3A)
1991	Chevrolet, Pontiac	N (LG0)(2.3A)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360623

138 CID Reman

2.3L

1994	Chevrolet	L (LG0)(2.3A)
1994	Pontiac, Chevrolet	N (LG0)(2.3A)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, P/S Pump Pulley, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360624

138 CID Reman

2.3L

1987-88	Pontiac, Oldsmobile, Buick	N (LD2)(2.3D)
---------	-------------------------------	---------------

Engine-Specific Content: Camshaft Housing, Crankshaft Housing, Front Cover, Oil Check Valve, Oil Pan, Oil Pump w/Screen, P/S Pump Pulley, Spark Plugs, Timing Chain Housing, Timing Chain Tensioner and Guides, Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360625

138 CID Reman

2.3L

1989 Pontiac, Oldsmobile, N (LD2)(2.3D)
Buick

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360626

138 CID Reman

2.3L

1990-91 Pontiac, Oldsmobile, N (LD2)(2.3D)
Buick
1990-91 Pontiac, Oldsmobile W (LD2)(2.3D)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360627

138 CID Reman

2.3L

1993 Pontiac, Oldsmobile N (LD2)(2.3D)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12361504

138 CID Reman

2.3L

1992 Pontiac, Oldsmobile N (LD2)(2.3D)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

INSTALLATION INSTRUCTIONS

This engine has been remanufactured subsequent to the model year of the vehicle and as such may incorporate design refinements not included in original service information (i.e., 1989 engines by incorporate design features normally associated with newer models). If future service is necessary for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle chassis service manual for proper repair procedures.

- After removing old engine, use new seals and gaskets and transfer all necessary components, such as oil fill tube and cap/indicator.
- Attach Quad IV engine decal (enclosed in instruction envelope).
- Install replacement engine and add 4 quarts of Starburst certified oil of a viscosity recommended for your climate, and prime oil system.
- Check oil level on dipstick and add oil as required to reach the full mark.

CAUTION: The oil pump in this engine must be primed before starting. Crank engine for a minimum of 30 seconds with the ignition system disconnected. Oil pressure warning light must go off (if equipped with a pressure gauge, the gauge must read normal pressure for that model year). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

24571996	138 CID New	2.3L
1994	Chevrolet	L (LG0)(2.3A)
1994	Pontiac, Oldsmobile	N (LG0)(2.3A)
Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump		
Replaces: 24574880		Replaced By:
Notes: Does not contain Flywhl, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.		
INSTALLATION INSTRUCTIONS		
Please Notes that instructions only apply to certain applications and are provided only as a clarification for adapting current model Goodwrench engines into past model applications.		
<ul style="list-style-type: none"> The mounting boss on the oil pan for the radiator outlet pipe bracket has been eliminated. This bracket does not require attachment on the Goodwrench engine. LG0 (2.3A) engines may require transferring crankshaft balancers. Ensure that the crankshaft balancer on the Goodwrench engine is the same diameter as the original balancer. If not, transfer the original balancer to the Goodwrench engine. Pontiac Grand Prix and Oldsmobile Cutlass Supreme with LD2 (2.3D) or LG0 (2.3A) engines require an M12 x 1.75 bolt (part number 22579611) along with the two included M12 x 1.75 engine lift bracket bolts, to attach the engine mount strut bracket to the engine drill out the hole (12.5MM) on the bracket to allow for the larger M12 x 1.75 bolts. (One bolt - 22579611 - is included in service engine installation kit, catalog group 0.010). Pontiac Grand Prix and Oldsmobile Cutlass Supreme only - The new Goodwrench engine requires transferring the water pump cover from the original engine. This is necessary to ensure that the water pump cover contains the nipple required for the heater hose. The water pump cover gaskets should be replaced at this time. (Gaskets are included in the service engine installation kit. See catalog group 0.010.) 		

24573746	138 CID New	2.3L
1995	Chevrolet, Pontiac	J (LD2)(2.3D) MJ1
1995	Pontiac, Oldsmobile, Buick	N (LD2)(2.3D)
Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump		
Notes: Does not contain Flywhl, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.		
INSTALLATION INSTRUCTIONS		
No special installation instructions are necessary. Please refer to the general installation procedure section of this book.		

GOODWRENCH SERVICE REPLACEMENT ENGINES

24575362

138 CID New

2.3L

1995 Chevrolet, Pontiac J (LD2)(2.3D) MN4

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

Notes: Does not contain Flywhl, Oil Fill Tube, C/case Vent Sys, Therm, Int or Exh Manif, Elec Ign Mod, Cr/shf Posn, Knock, Map, Cool Temp or Oil Lvl Sen.

INSTALLATION INSTRUCTIONS

Please Note that instructions only apply to certain applications and are provided only as a clarification for adapting current model Goodwrench engines into past model applications.

- The mounting boss on the oil pan for the radiator outlet pipe bracket has been eliminated. This bracket does not require attachment on the Goodwrench engine.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360467 **2.4L**
 146 CID New

1996	Chevrolet, Pontiac	J (LD9)
1996	Pontiac, Oldsmobile, Buick	N (LD9)(2.4T)

Engine-Specific Content: Camshaft Housing, Front Cover, Oil Check Valve, Oil Pan, P/S Pump Pulley, Spark Plugs, and Water Pump

Notes: Does not contain Flywheel, Oil Fill Tube, C/case Vent Sys, Thermostat, Int. or Exhaust Manifold, Elec. Ign. Mod, Crankshaft Posn, Knock, Map, Cool Temp or Oil Level Sensor. Order 11516479 self tapping screw for Cm/Shf Posn sensor

Replaces: 24573914

Replaced By: 12465099

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12462258 **2.4L**
 146 CID New

1997-98	Chevrolet, Pontiac	J (LD9)(2.4T)
1997-98	Chevrolet, Pontiac, Oldsmobile, Buick	N (LD9)(2.4T)
1999	Pontiac	N (LD9)(2.4T)

Engine-Specific Content: Front Cover, Oil Check Valve, Oil Pan, Water Pump, and Spark Plugs

Notes: Does not contain Flywheel, C/case Vent Sys, Thermostat, Int. or Exhaust Manifold, Elec. Ign. Mod, Crankshaft Posn, Knock, Map. Order 11516479 self tapping screw for Cm/Shf Posn Sensor. For 2nd design, see 12465154.

Replaces: 12363189

Replaced By: 12465153

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12465498 **2.4L**
 146 CID Reman

1999-2002	Chevrolet, Pontiac	J (LD9)
1999-2001	Oldsmobile	N (LD9)
1999	Chevrolet	N (LD9)
1999	Pontiac	N (LD9)
2000-01	Pontiac	N (LD9)

Engine-Specific Content: Oil Pan, Timing Chain & Housing, Spark Plugs, Water Pump, and P/S Pump Pulley

Notes: Does not include Flywheel, Crankcase, Thermostat, Intake or Exhaust Manifold, Electric Ignition Module, Crankshaft Posn., and Oil Level Sensors. For 1st design, see 12462258.

Replaces: 12465154, 88894199, 88890518

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351901

151 CID Reman

2.5L

1990	Chevrolet, Pontiac	A (LR8)(2.5R)
	Oldsmobile, Buick	
1990	Chevrolet	W (LR8)(2.5R)

Engine-Specific Content: Crankshaft Balancer, Front Cover, Internal Balancer, Oil Pan, and Valve Rocker Cover

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351904

151 CID Reman

2.5L

1986	Chevrolet, Pontiac	A (LR8)(2.5R)
	Oldsmobile, Buick	
1986	Chevrolet	P (LR8)(2.5R)

Engine-Specific Content: Crankshaft Balancer, Front Cover, Internal Balancer, Oil Pan, and Valve Rocker Cover

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351905

151 CID Reman

2.5L

1985	Chevrolet, Pontiac Oldsmobile, Buick	A (LR8)(2.5R)
1985	Pontiac	P (LR8)(2.5R)
1985	Chevrolet, Buick	X (LR8)(2.5R)

Engine-Specific Content: Crankshaft Balancer, Front Cover, Internal Balancer, Oil Pan, and Valve Rocker Cover

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351906	151 CID Reman	2.5L
-----------------	---------------	-------------

1984	Chevrolet, Pontiac Oldsmobile, Buick	A, X (LR8)(2.5R)
1984	Pontiac	P (LR8)(2.5R)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351907

151 CID Reman

2.5L

1982-83 Chevrolet, Pontiac A, X (LR8)(2.5R)
Oldsmobile, Buick

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351909

151 CID Reman

2.5L

1989 Pontiac, Oldsmobile N (L68)(2.5U)
Buick

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351910

151 CID Reman

2.5L

1988

Pontiac, Oldsmobile
Buick

N (L68)(2.5U)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351911

151 CID Reman

2.5L

1987 Pontiac, Oldsmobile N (L68)(2.5U) w/M.T.
Buick

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351912

151 CID Reman

2.5L

1987 Pontiac, Oldsmobile N (L68)(2.5U) w/A. Trans
Buick

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351913

151 CID Reman

2.5L

1985-86

Pontiac, Oldsmobile
Buick

N (L68)(2.5U)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351914

151 CID Reman

2.5L

1989-90	Chevrolet, GMC	M1, S1 (LN8)(2.5E)
1989-91	Chevrolet, GMC	Z1 (LN8)(2.5E)
1991	Chevrolet, Oldsmobile GMC	S1 (LN8)(2.5E)

Engine-Specific Content: Front Cover and Oil Pan

Notes: Must purchase balancer separately, not included in assembly components.

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351915

151 CID Reman

2.5L

1988

Chevrolet, GMC

M1, ST1, Z1 (LN8)(2.5E)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351917

151 CID Reman

2.5L

1986

Chevrolet

M1, ST1 (LN8)(2.5E)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351918

151 CID Reman

2.5L

1985

Chevrolet

M1, ST1 (LN8)(2.5E)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351919

151 CID Reman

2.5L

1988	Chevrolet, Pontiac, Oldsmobile, Buick	A (LR8)(2,5R)
1988	Pontiac	P (LR8)(2.5R)

Engine-Specific Content: Front Cover

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351920

151 CID Reman

2.5L

1990

Pontiac, Oldsmobile,
Buick

N (L68)(2.5U)

Engine-Specific Content: Front Cover

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351921

151 CID Reman

2.5L

1991

Oldsmobile, Buick

N (L68)(2.5U)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351923

151 CID Reman

2.5L

1991-93	Chevrolet, Oldsmobile, GMC	S1 (L38)(2.5A)
1991-93	GMC	Z1 (LLV)(L38)(2.5A)

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12351924

151 CID Reman

2.5L

1989 Chevrolet, Pontiac, A (LR8)(2.5R)
Oldsmobile, Buick

Engine-Specific Content: Front Cover and Oil Pan

INSTALLATION INSTRUCTIONS

The Goodwrench 2.5 engine has been remanufactured subsequent to the model year of the vehicle and may incorporate design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.

Before installing this engine, refer to the appropriate vehicle service chassis manual for proper repair procedures and owner's manual for capacities.

- Initially add 3 quarts of Starburst certified oil in viscosity suitable to your climate conditions. Prime system and check oil level on dipstick. Add oil as required to reach full mark.
- Use new seals and gaskets. Transfer all necessary components to the replacement engine. Thoroughly clean all old parts to avoid possible contamination and leaks.
- If harmonic damper hub is grooved in seal contact area, replace the damper to prevent oil leaks.
- The rear most intake manifold bolt **MUST** go through the engine lift bracket or an equivalent thickness spacer. Failure to do so permits the bolt to contact the #8 push rod resulting in lifter noise and possible damage to the engine.
- Rocker cover installation: A) use RTV on dimpled covers, B) use cork/rubber gasket (with compression limiters) with non-hemmed holes on covers, C) use silicone/steel reinforced gasket with non-dimpled, non-hemmed rocker covers.
- Attach the enclosed decal to clean rocker cover.
- Install the appropriate bushing in the crank end depending on if equipped with automatic or manual transmission.
- Check the cooling system for proper operation.

CAUTION: The oil pump in this engine must be primed before starting engine. Turn engine for a minimum of 30 seconds with the coil or injector wire disconnected. Oil pressure warning light must go off (if equipped with a pressure gage, the gage must read 30 PSI minimum). **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

Straight 4 In-Line Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.



GOODWRENCH SERVICE REPLACEMENT ENGINES

12585215

173 CID New

2.8L

2004

Chevrolet, GMC

ST1 (LK5)(2.8-8) MA5, M30, JJA

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

Straight 5 In-Line Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12585341	214 CID New	3.5L
-----------------	-------------	-------------

2004	Chevrolet, GMC	S1 (L52) M30, MA5 - DOHC
------	----------------	--------------------------

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12585342	214 CID New	3.5L
-----------------	-------------	-------------

2004	Chevrolet, GMC	T1 (L52) - DOHC
------	----------------	-----------------

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

V6 Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.

GOODWRENCH SERVICE REPLACEMENT ENGINES

10054502	173 CID New	2.8L
-----------------	-------------	-------------

1982-86	Chevrolet, Pontiac	A (LE2)(2.8X)
1982-85	Chevrolet, Buick	X (LE2)(2.8X)
1982-84	Pontiac, Oldsmobile	X (LE2)(2.8X)
1985-86	Buick	A (LE2)(2.8X)
1985-96	Oldsmobile	A (LE2)(2.8X)

Engine-Specific Content: Flywheel, Oil Pan, Torsional Damper, and Valve Covers

Replaces: 10065260

Replaced By:

Notes: Automatic Transmission Only

INSTALLATION INSTRUCTIONS

- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts.
- This engine is built with current valve rocker cover. It may be necessary to use covers from replaced engine.
- This engine incorporates a 'balanced' automatic flywheel, part number 14018713. If replacement is necessary, replace with part number 14018713.

12507648	173 CID New	2.8L
-----------------	-------------	-------------

1982-86	Chevrolet, GMC	T1 (LL2)(2.8R)(LR2)(2.8B)
---------	----------------	---------------------------

Engine-Specific Content: Flywheel, Oil Pan, Front Cover, Oil Fill Cap, Torsional Damper, and Valve Covers

Notes: Automatic Transmission Only

INSTALLATION INSTRUCTIONS

- This engine incorporates a 'balanced' automatic flywheel, part number 14100557. If replacement is necessary, replace with part number 14100557.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts.
- This engine is built with current valve rocker cover. It may be necessary to use covers from replaced engine.
- On fuel injection models, plug fuel hole with:
 - 1 of 14064231 Cover - Fuel Pump opening
 - 2 of 11500914 Bolts
 - 2 of 580379 Washers
 - RTV Sealer

GOODWRENCH SERVICE REPLACEMENT ENGINES

12523277 **2.8L**
 173 CID New

1987-89	Chevrolet, Pontiac	F (LB8)(2.8S) A/Trans
1987-89	Chevrolet, GMC	ST1 (LL2)(2.8R)(2.8S) A. Trans

Engine-Specific Content: Oil Pan, Valve Covers, Flywheel, and Torsional Damper

Notes: Automatic Transmission Only

INSTALLATION INSTRUCTIONS

- This engine incorporates a 'balanced' automatic flywheel, part number 14097667. If replacement is necessary, replace with part number 14097667.
- This engine is built with 1992 production parts. For service, use 1992 parts. Covers from replaced engine may have to be used.
- On "F" cars and "S" trucks: A) remove oil pan and replace with part number 10078999, B) remove oil pump screen assembly and replace with part number 10118624, C) use oil level indicator from replaced engine.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts.

12523279 **2.8L**
 173 CID New

1987-89	Chevrolet, Pontiac	F (LB8)(2.8S), M. Trans
1987-90	Chevrolet, GMC	ST1 (LL2), M. Trans
1991-93	Chevrolet, GMC	S1 (LL2)(2.8R), M. Trans (ML3)

Engine-Specific Content: Oil Pan, Valve Covers, Flywheel, and Torsional Damper

Notes: Manual Transmission Only

INSTALLATION INSTRUCTIONS

- This engine incorporates a 'balanced' flywheel, part number 14100556. If replacement is necessary, replace with part number 14100556.
- On "F" cars, remove flywheel and replace with part number 14100559.
- This engine is built with 1992 production parts. When servicing, use 1992 parts. Valve covers from replaced engine may have to be used.
- On "F" cars and "S" trucks: A) remove oil pan and replace with part number 10078999, B) remove oil pump screen assembly and replace with part number 10118624, C) use oil level indicator from replaced engine.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12371987 191 CID Reman **3.1L**

1997 Chevrolet, Oldsmobile N (L82)

Engine-Specific Content: Front Cover, Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Lower Intake Manifold, Engine Oil and Additive

Replaces: **Replaced By:** 89037574

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12480240 191 CID New **3.1L**

1998-99 Chevrolet, Oldsmobile N (L82)

Engine-Specific Content: Front Cover, Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Lower Intake Manifold, Engine Oil and Additive

Replaces: **Replaced By:** 89037575

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12480242 191 CID New **3.1L**

1994-95 Chevrolet, Pontiac U Van (LG6)(3.1D) MD9, C40, C67
1994-95 Oldsmobile U Van (LG6)(3.1D) MD9, C67

Engine-Specific Content: Front Cover and Pointer, Lower Intake Manifold, Oil Pan, and Valve Covers

Replaces: 12522926 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12513152 191 CID New **3.1L**

1990 Chevrolet, Pontiac U (LG6)(3.1D)
Oldsmobile

Engine-Specific Content: Front Cover, Lower Intake Manifold, Oil Pan, and Valve Covers

INSTALLATION INSTRUCTIONS

- This engine incorporates 1993 production parts. When servicing internal components and the dipstick and tube assembly, use 1993 LG6 service parts.
- The engine is built to production point of build torque specifications, loss of some bolt torque is normal. It is not necessary to retorque any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12513153 **3.1L**
 191 CID New

1990	Chevrolet, Pontiac, Oldsmobile, Buick	W (LH0)(3.1T)
1991	Buick	W19 Type 1 VIN 400001 thru 800000

Engine-Specific Content: Front Cover, Lower Intake Manifold, Oil Pan, and Valve Covers

Notes: If engine is received without dampener, must order part number 10166353.

INSTALLATION INSTRUCTIONS

- This engine incorporates 1993 production parts. When servicing internal components and the dipstick and tube assembly, use 1993 LH0 service parts.
- The engine is built to production point of build torque specifications, loss of some bolt torque is normal. It is not necessary to retorquer any bolts.

12522927 **3.1L**
 191 CID New

1991-92	Chevrolet, Pontiac	J (LH0)(3.1T)
1991-92	Pontiac, Oldsmobile	W (LH0)(3.1T)
1991	Chevrolet	L (LH0)(3.1T)
1991-92	Chevrolet	W (LH0)(3.1T) (exc. N14)
1991	Buick	W (LH0)(3.1T) Type 2 VIN from 800001
1992-93	Chevrolet	L (LH0)(3.1T)
1992	Buick	W (LH0)(3.1T)
1993	Chevrolet, Pontiac	J (LH0)(3.1T)
1993	Chevrolet	W (LH0)(3.1T) (exc. N14, NB2)
1993	Pontiac, Oldsmobile, Buick	W (LH0)(3.1T) (exc. NB2)
1994	Chevrolet, Pontiac	J (LH0)(3.1T) MD9, MG2
1994	Chevrolet	W (LH0)(3.1T) M13, NB2, NA5

Engine-Specific Content: Front Cover, Lower Intake Manifold, Oil Pan, and Valve Covers

Replaces: 12516160

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12522928 **3.1L**
 191 CID New

1993-95	Oldsmobile, Buick	W (L82)(3.1M) M13
1994-95	Oldsmobile, Buick	A (L82)(3.1M)
1994-95	Chevrolet	L (L82)(3.1M) M13
1994-95	Pontiac, Oldsmobile, Buick	N (L82)(3.1M)
1994-95	Pontiac	W (L82)(3.1M)
1995	Chevrolet	W (L82)(3.1M)

Engine-Specific Content: Front Cover, Lower Intake Manifold, and Valve Covers

Replaces: **Replaced By: 89037572**

INSTALLATION INSTRUCTIONS

This engine includes an oil pan with an oil level sensor. For vehicles that are not equipped for an oil level sensor, use sensor as plug for hole, or use oil pan from replaced engine.

12539087 **3.1L**
 191 CID New

1996	Pontiac	N (L82) VB1
1996-98	Pontiac, Buick	N (L82)(3.1M)
1996-97	Chevrolet, Pontiac, Oldsmobile, Buick	W (L82)(3.1M) M13
1996	Oldsmobile, Buick	A (L82)(3.1M)
1996	Chevrolet	L (L82)(3.1M) M13
1996-98	Oldsmobile	N (L82)(3.1M)

Engine-Specific Content: Front Cover, Lower Intake Manifold, Oil Pan, Valve Covers, Oil Level Sensor, Engine Oil and Additive

Replaces: **Replaced By: 89037573**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894110 **3.1L**
 191 CID New

1999	Chevrolet, Oldsmobile	N (LG8)(3.1J) SFI, NC1
------	-----------------------	------------------------

Engine-Specific Content: Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Lower Intake Manifold, Engine Oil and Additive

Replaces: 12480891 **Replaced By: 89038376**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894112

191 CID New

3.1L

2000	Pontiac, Buick	W (LG8)(3.1J) SFI, NC1, NF4
2000	Chevrolet	N, W (LG8)(3.1J) SFI, NC1, NF4
2001	Chevrolet	W (LG8) NC1, NF4, NF7

Engine-Specific Content: Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Lower Intake Manifold, Engine Oil and Additive

Replaces: 88893923, 12568295**Replaced By:** 89038377

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017454

191 CID New

3.1L

2003-05	Buick	W (LG8)
2003	Chevrolet	N (LG8)
2003	Pontiac	W (LG8)

Engine-Specific Content: Front Cover, Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensors, Oil Filter Cap, and Lower Intake Manifold

Replaces: 88984280**Replaced By:**

Notes: When replacing a 2003MY engine, use the oil pan that corresponds with that particular application.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89038378

191 CID Reman

3.1L

2000-02	Chevrolet	N (LG8)
2000-02	Pontiac, Buick	W (LG8)
2000	Chevrolet	W (LG8) NF2

Engine-Specific Content: Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, and Lower Intake Manifold

Replaces: 88894111, 88893298, 12568294**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89037576

191 CID Reman

3.1L

1998-99	Chevrolet, Pontiac, Buick	W (L82)
---------	------------------------------	---------

Engine-Specific Content: Front Cover, Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Lower Intake Manifold, Engine Oil and Additive

Replaces: 12480241**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12356519

204 CID Reman

3.3L

1989 Oldsmobile, Buick A, N (LG7)(3.3N)

Engine-Specific Content: Front Cover and Oil Pump

Notes: For "N" car applications, transfer oil filter adapter from old engine or order new as detailed in the instructions. Does not contain Rocker Covers, Oil Pan, Manifolds or Balancer.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3300 engine decals (enclosed in instructions envelope) to clean valve covers.

Oil Filter Adapters: For "N" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239 for 1989-91 or 24500718 for 1992-93 models.

CAUTION: The oil pump in this engine must be primed before starting. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12356520

204 CID Reman

3.3L

1990 Oldsmobile, Buick A, N (LG7)(3.3N)

Engine-Specific Content: Front Cover and Oil Pump

Notes: For "N" car applications, transfer oil filter adapter from old engine or order new as detailed in the instructions. Does not contain Rocker Covers, Oil Pan, Manifolds or Balancer.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3300 engine decals (enclosed in instructions envelope) to clean valve covers.

Oil Filter Adapters: For "N" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239 for 1989-91 or 24500718 for 1992-93 models.

CAUTION: The oil pump in this engine must be primed before starting. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12356521

204 CID Reman

3.3L

1991 Oldsmobile, Buick A, N (LG7)(3.3N)

Engine-Specific Content: Front Cover and Oil Pump

Notes: For "N" car applications, transfer oil filter adapter from old engine or order new as detailed in the instructions. Does not contain Rocker Covers, Oil Pan, Manifolds or Balancer.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3300 engine decals (enclosed in instructions envelope) to clean valve covers.

Oil Filter Adapters: For "N" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239 for 1989-91 or 24500718 for 1992-93 models.

CAUTION: The oil pump in this engine must be primed before starting. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12356522

204 CID Reman

3.3L

1992	Oldsmobile, Buick	A, N (LG7)(3.3N)
1992	Pontiac	N (LG7)(3.3N)

Engine-Specific Content: Front Cover and Oil Pump

Notes: For "N" car applications, transfer oil filter adapter from old engine or order new as detailed in the instructions. Does not contain Rocker Covers, Oil Pan, Manifolds or Balancer.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3300-engine decals (enclosed in instructions envelope) to clean valve covers.

Oil Filter Adapters: For "N" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239 for 1989-91 or 24500718 for 1992-93 models.

CAUTION: The oil pump in this engine must be primed before starting. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12356523

204 CID Reman

3.3L

1993	Oldsmobile, Buick	A, N (LG7)(3.3N)
1993	Pontiac	N (LG7)(3.3N)

Engine-Specific Content: Front Cover and Oil Pump

Notes: For "N" car applications, transfer oil filter adapter from old engine or order new as detailed in the instructions. Does not contain Rocker Covers, Oil Pan, Manifolds or Balancer.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3300-engine decals (enclosed in instructions envelope) to clean valve covers.

Oil Filter Adapters: For "N" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239 for 1989-91 or 24500718 for 1992-93 models.

CAUTION: The oil pump in this engine must be primed before starting. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12537812 **3.4L**
207 CID New

1991-93	Chevrolet, Pontiac	W (LQ1) M27
1991-92	Oldsmobile	W (LQ1) M27

Engine-Specific Content: Crankshaft Balancer, Flywheel Assembly, Oil Pan, Oil Level Indicator and Tube, Front Cover, Timing Belt System, Camshaft with Hsg. and Cover, Crank and Cam Posn. Sensors, and Lower Intake Manifold

Replaces: 24503079

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894033 **3.4L**
207 CID New

2000	Pontiac	N, U (LA1) NF2
2000	Chevrolet	W (LA1) NF2
2000	Chevrolet, Oldsmobile	U (LA1) NF2
2000	Oldsmobile	N (LA1) NA7, NF2
2001-02	Pontiac	B, N, U (LA1) NF7
2001-02	Chevrolet	U, W (LA1) NF7, NF4
2001-02	Oldsmobile	U (LA1) NF7
2002	Buick	B (LA1) NF7

Engine-Specific Content: Front Cover, Oil Pan, and Valve Covers

Replaces: 88893925, 12569554

Replaced By: 89038388

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894034 **3.4L**
207 CID New

2001-02	Pontiac	B (LA1) KC4, NC8
2001-02	Pontiac	B (LA1) NC8 (exc. KC4)
2001	Pontiac	U (LA1) NC8
2001-02	Chevrolet, Oldsmobile	U (LA1) NC8
2002	Buick	B (LA1) NC8
2002	Pontiac	U (LA1) NC8, KC4
2002	Pontiac	U (LA1) NC8 (exc. KC4)
2002	Pontiac	U (LA1) NT3

Engine-Specific Content: Front Cover, Oil Pan, and Valve Covers

Replaces: 12569555

Replaced By: 89038387

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88984251 207 CID New **3.4L**

1999	Pontiac, Oldsmobile	N (LA1)
1999	Chevrolet, Pontiac, Oldsmobile	U (LA1)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, and Valve Rocker Covers

Replaces: 12480881

Replaced By: 89038384

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88984287 207 CID New **3.4L**

2003	Pontiac	U (LA1) NT3
------	---------	-------------

Engine-Specific Content: Oil Pump, Front Cover, Oil Pan, Oil Filter, Valve Rocker Covers, Oil Level Sensor, Oil Fill Cap, and Lower Intake Manifold

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88984288 207 CID New **3.4L**

2003	Chevrolet	W (LA1)
2003-04	Oldsmobile	N (LA1)
2003-05	Pontiac	N (LA1)

Engine-Specific Content: Oil Pan, Oil Filter, and Rocker Covers

Replaces:

Replaced By: 89017445

Notes: When replacing a 2003MY engine, use the oil pan that corresponds with that particular application.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017444 207 CID New **3.4L**

2003-05	Pontiac, Buick	B (LA1)
2003-04	Oldsmobile	U (LA1)
2003-05	Chevrolet, Pontiac	U (LA1)
2004-05	Chevrolet	W (LA1)

Engine-Specific Content: Oil Pan, Oil Filter, and Rocker Covers

Replaces: 88984289, 88984286

Replaced By:

Notes: When replacing a 2003MY engine, use the oil pan that corresponds with that particular application.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017445 **3.4L**
207 CID New

2003	Chevrolet	W (LA1)
2003-04	Pontiac, Oldsmobile	N (LA1)

Engine-Specific Content: Oil Pan, Oil Filter, and Rocker Covers

Replaces: 88984288 **Replaced By:**

Notes: When replacing a 2003MY engine, use the oil pan that corresponds with that particular application.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89038381 **3.4L**
207 CID Reman

1996	Chevrolet, Pontiac, Oldsmobile	Z (LA1)
1997	Chevrolet, Pontiac Oldsmobile	U (LA1)

Engine-Specific Content: Front Cover, Oil Pan, and Valve Covers

Replaces: 88984249, 12539088 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89038382 **3.4L**
207 CID Reman

1998	Chevrolet, Pontiac, Oldsmobile	U (LA1)
------	-----------------------------------	---------

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, and Valve Rocker Covers

Replaces: 88984250, 12371991 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89038385 **3.4L**
207 CID Reman

2000	Chevrolet	W (LA1)(3.4E) MFI HO (NC1)
2000	Pontiac, Oldsmobile	N (LA1)(3.4E) MFI HO (NC1)
2000	Chevrolet, Pontiac, Oldsmobile	U (LA1)(3.4E) MFI HO (NC1)

Engine-Specific Content: Oil Pan, Oil Filter, and Rocker Covers

Replaces: 88893924, 12482058 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12458123	214 CID New	3.5L
-----------------	-------------	-------------

1999-2000	Oldsmobile	W (LX5)(3.5H) MFI DOHC (NF2)
-----------	------------	------------------------------

Engine-Specific Content: Crankshaft Balancer Assembly, Crank & Cam Posn. Sensors, Camshaft Covers, Front Cover Assembly, Filter, Level Indicator Assembly, Oil Level SW, Oil Pan, Flywheel, Spark Plugs, Engine Oil Additive, Water Pump/Pulley Assembly, Water Outlet, and Thermostat

Notes: Does not include Intake Manifold/Thermal Body Assemblies.

Replaces: 12458066

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12458124	214 CID New	3.5L
-----------------	-------------	-------------

2000-02	Oldsmobile	W (LX5)(3.5H) MFI DOHC (NC1)
2001-02	Oldsmobile	G (LX5)(3.5H) MFI DOHC (NC1)

Engine-Specific Content: Balancer, Flywheel, Oil Pan, Oil Pump, and Oil Filter

Notes: For engines with physical ID of KWA or KXA, reuse Thermostat Housing.

Replaces: 12564895

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12593699 214 CID New **3.6L**

2004-05 Cadillac D (LY7) M82, MV1

Engine-Specific Content: Oil Pan and Front Cover

Replaces: 12585320 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12593700 214 CID New **3.6L**

2005 Cadillac D,E (LY7)

Engine-Specific Content: Oil Pan and Front Cover

Replaces: 12585321 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12595157 214 CID New **3.6L**

2005 Buick B,W (LY7)

Engine-Specific Content: Oil Pan and Front Cover

Replaces: 12585319 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360021

231 CID Reman

3.8L

1989	Oldsmobile, Buick	C, E, H (LN3)(3.8C)
1989	Pontiac	H (LN3)(3.8C)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Oil Pump with Gears and Cover.

Notes: For "E" car applications, transfer oil filter adapter from old engine or order new. Engine does not include Rocker Covers, Oil Pan, Intake Manifold or Exhaust Manifold.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360022

231 CID Reman

3.8L

1990	Oldsmobile, Buick	C, E, H (LN3)(3.8C)
1990	Pontiac	H (LN3)(3.8C)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Oil Pump with Gears and Cover

Notes: For "E" car applications, transfer oil filter adapter from old engine or order new. Engine does not include Rocker Covers, Oil Pan, Intake Manifold or Exhaust Manifold.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12360023

231 CID Reman

3.8L

1991 Pontiac, Oldsmobile H (LN3)(3.8C)
Buick

Engine-Specific Content: Crankshaft Balancer, Crank and Cam Posn Sensor, Engine Coolant Temp Sensor, Front Cover, Int Air Temp Sensor, Map Sensor, Oil Level Sensor, Oil Pressure Sensor, Spark Plugs, Thermostat and Water Pump

Notes: Does not include Intake Manifold, Exhaust Manifold and attaching parts.

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360686

231 CID Reman

3.8L

1986 Oldsmobile, Buick A, C, E, H (LG2)(3.8B)

Engine-Specific Content: Front Cover and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

- For 1986-87 "E" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12360687

231 CID Reman

3.8L

1985 Oldsmobile, Buick A, C (LN3)(231-3)

Engine-Specific Content: Front Cover

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12362213 **3.8L**
231 CID Reman

1990-91	Buick	W (L27)
1991	Oldsmobile, Buick	C, E (L27)
1991	Pontiac, Oldsmobile,	H (L27)
	Buick	

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.
Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.
- For 1988-91 "E" car applications, transfer the oil filter adapter from the old engine or use new part number 25537239.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12362214 **3.8L**
231 CID Reman

1992	Oldsmobile, Buick	C, E, H (L27)(3.8L)
1992	Pontiac	H (L27)(3.8L)
1992	Buick	W (L27)(3.8L)
1992	Chevrolet, Pontiac,	U Van (L27)(3.8L)
	Oldsmobile	

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.
Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.
- For 1992 "E" car applications, transfer the oil filter adapter from the old engine or use new part number 24501299 and bolts 25519262.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12362215 231 CID Reman **3.8L**

1993	Oldsmobile, Buick	C (L27)(3.8L)
1993	Pontiac, Oldsmobile, Buick	H (L27)(3.8L)
1993	Buick	W (L27)(3.8L)
1993	Chevrolet, Pontiac, Oldsmobile	U Van (L27)(3.8L)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.
Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.
- For 1993-95 "W" and "Z" car applications, transfer the oil filter adapter from the old engine or use new part number 24501300 and studs 24500567.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12362216 231 CID Reman **3.8L**

1994	Oldsmobile, Buick	C, H (L27)(3.8L)
1994	Pontiac, Oldsmobile, Buick	H (L27)(3.8L)
1994	Buick	W (L27)(3.8L)
1994	Chevrolet, Pontiac, Oldsmobile	U Van (L27)(3.8L)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.
Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.
- For 1993-95 "W" and "Z" car applications, transfer the oil filter adapter from the old engine or use new part number 24501300 and studs 24500567.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12362217

231 CID Reman

3.8L

1995	Buick	H, W (L27)(3.8L)
1995	Chevrolet, Pontiac, Oldsmobile	U Van (L27)(3.8L)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

- Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.
Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.
- For 1993-95 "W" and "Z" car applications, transfer the oil filter adapter from the old engine or use new part number 24501300 and studs 24500567.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12362218

231 CID Reman

3.8L

1991-92	Buick	C (L67)(3.8L)
1992	Oldsmobile	C (L67)(3.8L)
1992	Pontiac	H (L67)(3.8L)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12362219

231 CID Reman

3.8L

1993	Buick, Oldsmobile,	C (L67)(3.8L)
1993	Pontiac	H (L67)(3.8L)

Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Timing Chain Dampener, and Oil Pump

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12362220	231 CID Reman	3.8L
1995	Buick	G (L67)
1994	Oldsmobile, Buick	C (L67)
1994	Pontiac	H (L67)
Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Oil Pump w/Gears, Timing Chain Dampener, and Oil Pump		
Notes: 1 st design has 5/16" oil pan bolts and 3-bolt cam thrust plate. 2 nd design, see 12362221.		
INSTALLATION INSTRUCTIONS Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations. Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.		
CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

12362221	231 CID Reman	3.8L
1995	Oldsmobile, Buick	C (L67)(3.8-1)
1995	Pontiac, Oldsmobile	H (L67)(3.8-1)
1995	Buick	G (L67)(3.8-1)*
Engine-Specific Content: Balance Shaft, Front Cover, Oil Filter Adapter, Oil Pump w/Gears, Timing Chain Dampener, and Oil Pump		
Notes: *2 nd design has 1/4" Oil Pan Bolts and 2-bolt Cam Thruster Plate; 1 st design, see 12362220.		
INSTALLATION INSTRUCTIONS Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations. Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.		
CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

GOODWRENCH SERVICE REPLACEMENT ENGINES

12481315

231 CID New

3.8L

2000-04	Buick	C (L36)(3.8K)
2000-04	Pontiac, Buick	H (L36)(3.8K)

Engine-Specific Content: Flywheel, Oil Pan, Lower Intake Manifold, Front Cover, Water Pump, Balancer, and Crank & Cam Posn. Sensors

Replaces: 12564295**Replaced By:** 89017668

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12482057

231 CID New

3.8L

2000-03	Pontiac	H (L67)(3.8-1) SFI, SC
2000-04	Buick	C (L67)(3.8-1) SFI, SC

Engine-Specific Content: Balancer, Flywheel, Oil Pan, Front Cover, Oil Filter, Lower Intake, Valve Covers, Crank & Cam Posn. Sensors, and Oil Level Sensor

Replaces: 12568293**Replaced By:** 89017665

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017416

231 CID New

3.8L

2004

Pontiac

W (L32)

Replaces:
Replaced By: 89017666

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

89017667

231 CID New

3.8L

1996-99	Buick	C (L67)(3.8-1)
1996-99	Buick	G (L67)(3.8-1)
1996-99	Pontiac, Oldsmobile	H (L67)(3.8-1)
1997-2003	Pontiac	W (L67)(3.8-1)
1997-2004	Buick	W (L67)(3.8-1)
2004-05	Chevrolet	W (L67)(3.8-1)

Engine-Specific Content: Balancer, Crank & Cam Posn. Sensors, Front Cover, Flywheel, Lower Intake Manifold, Valve Covers, Oil Level Sensor, Oil Pan, and Water Pump

Notes: Does not contain Exhaust Manifold and attached parts. May be necessary to replace Oil Level Sensor with new or Trans Original Sens. Engine comes with 97-00 Flywheel.

Replaces: 12480888, 12371978, 24508875

Replaced By:

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017669

231 CID New

3.8L

2005

Chevrolet

W (L26)

Engine-Specific Content: Crank Balancer, Flywheel, Oil Pan, Front Cover, Oil Filter, Lower Intake, Valve Covers, Crank & Cam Posn. Sensor, and Oil Level Sensor

Replaces: 12480889, 12480887, 89017262**Replaced By:**

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

89017670

231 CID New

3.8L

2004

Pontiac, Buick

W (L26)

Engine-Specific Content: Crank Balancer, Flywheel, Oil Pan, Front Cover, Oil Filter, Lower Intake, Valve Covers, Crank & Cam Posn. Sensor, and Oil Level Sensor

Replaces: 12480889, 12480887, 89017262**Replaced By:**

INSTALLATION INSTRUCTIONS

Do not remove the engine vehicle identification plate from the original engine. Identification of the engine being installed must comply with any applicable state laws or regulations.

Goodwrench Decals: Attach two 3800-engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Refer to owner's manual for proper oil type and quantity. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12361241

262 CID Reman

4.3L

1985	Chevrolet, Pontiac	B (LB4)(4.3Z)
1985	Chevrolet	G (LB4)(4.3Z)
1985	Chevrolet, GMC	C1,2 G1,2 K1, M1 (LB1)(4.3N)

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12361243

262 CID Reman

4.3L

1987-90	Chevrolet	B (LB4)(4.3Z)
1987-88	Chevrolet	G (LB4)(4.3Z)
1987	Pontiac	G (LB4)(4.3Z)
1987	Chevrolet, GMC	CK1, R1,2, V1, RV1 (LB4)(4.3Z)
1987-89	Chevrolet, GMC	M1 (LB4)
1988	Chevrolet, GMC	CK1,2,3, V2 (LB4)(4.3Z)
1988-91	Chevrolet, GMC	ST1 (LB4)(4.3Z)
1989-91	Chevrolet, GMC	CK1,2 (LB4)(4.3Z) Exc. Emis. above 8500lb. GVW (NA4)
1987-90	Chevrolet, GMC	G1,2,3 (LB4)(4.3Z)
1990	Chevrolet, GMC	LM1 (LB4)(4.3Z)
1991	Chevrolet, GMC	G1,2,3 (LB4)(4.3Z) Exc. Emis. above 8500lb. GVW (NA4)

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12361247

262 CID Reman

4.3L

1992	Chevrolet	B (LB4)(4.3Z)
1992	Chevrolet, GMC	CK1, ST1 (LB4)(4.3Z)
1992	Chevrolet, GMC	CK2 (LB4) NA1
1992	Chevrolet, GMC	LM1 (LB4)
1992	Chevrolet, GMC	G1,2,3 (LB4)(4.3Z) Exc. Emiss. above 8500lb. GVW (NA4)

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve. Engine not used on GMC Typhoon and Syclone models.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12361248

262 CID Reman

4.3L

1992	Chevrolet	LM1, ST1 (L35)(4.3W)
------	-----------	----------------------

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12361249	262 CID Reman	4.3L
1993	Chevrolet, GMC	ST1 (LB4)(4.3Z)
<i>Engine-Specific Content:</i> Oil Pump		
Notes: Includes 21-PSI Oil Pressure Bypass Valve. Engine not used on GMC Typhoon and Syclone models.		
INSTALLATION INSTRUCTIONS		
Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.		
<ul style="list-style-type: none"> • Replacement of oil related parts: If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler MUST BE REPLACED and the oil lines and remote filter adapter MUST BE REMOVED from the vehicle and thoroughly flushed or replaced. <u><i>Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.</i></u> • Intake Manifold: For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent MUST BE APPLIED to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders. • Front Covers: 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred. 		
CAUTION: The oil pump in this engine must be primed before starting engine. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

12361251	262 CID Reman	4.3L
1993	Chevrolet, GMC	CK1,2 (LB4)(4.3Z) NA5
1993	Chevrolet, GMC	G1,2,3 (LB4)(4.3Z) (exc. NA4)
1993	Chevrolet, GMC	LM1 (LB4)(4.3Z)
<i>Engine-Specific Content:</i> Oil Pump		
Notes: Includes 21-PSI Oil Pressure Bypass Valve.		
INSTALLATION INSTRUCTIONS		
Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.		
<ul style="list-style-type: none"> • Replacement of oil related parts: If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler MUST BE REPLACED and the oil lines and remote filter adapter MUST BE REMOVED from the vehicle and thoroughly flushed or replaced. <u><i>Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.</i></u> • Intake Manifold: For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent MUST BE APPLIED to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders. • Front Covers: 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred. 		
CAUTION: The oil pump in this engine must be primed before starting engine. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

GOODWRENCH SERVICE REPLACEMENT ENGINES

12361252

262 CID Reman

4.3L

1993

Chevrolet

B (LB4)(4.3Z)

Engine-Specific Content: Oil Pump**Notes:** Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12361253

262 CID Reman

4.3L

1993

Chevrolet, GMC

LM1, ST1 (L35)(4.3W)

Engine-Specific Content: Oil Pump**Notes:** Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12363728

262 CID Reman

4.3L

1994	Chevrolet, GMC	CK1,2 (LB4)(4.3Z)
1994	Chevrolet, GMC	ST1 (LB4)(4.3Z) MY2, M30
1994	Chevrolet, GMC	LM1 (LB4)(4.3Z) M30

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve. Does not include Oil Pan or Rocker Covers, order separately.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12363729

262 CID Reman

4.3L

1994	Chevrolet GMC	G3 (LB4)(4.3Z) w/NAI Emis. Sys (under 8500lb. GVM)
1994	Chevrolet, GMC	G1,2 (LB4)(4.3Z), M30

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12363730

262 CID Reman

4.3L

1994	Chevrolet, GMC	LM1 (L35)(4.3W) M30
1994	Chevrolet	ST1 (03-53)(L35)(4.3W) MY2, M30
1994	Chevrolet, GMC	ST1 (06-16)(L35)(4.3W) M30 (exc. CTF)

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12366016

262 CID Reman

4.3L

1995	Chevrolet, GMC	CK1,2 (LB4)(4.3Z)
1995	Chevrolet, GMC	G1,2 (LB4)(4.3Z) M30
1995	Chevrolet, GMC	ST1 (LB4)(4.3Z)
1995	Chevrolet, GMC	G3 (LB4)(4.3Z) w/NAI Emis. Sys (under 8500lb. GVM) M30 (A/Trans)

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12366017

262 CID Reman

4.3L

1994	Chevrolet, GMC	ST1 (L35)(4.3W) M30, CTF
1995	Chevrolet, GMC	ST1 (L35)(4.3W) M50, M30, NM8 (exc. NM8)
1995	Chevrolet, GMC	ST1 (L35)(4.3W) M50, NM8, W99 (exc. NM8)
1995	Chevrolet, GMC	LM1 (L35) M30

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12369214

262 CID Reman

4.3L

1997-98	Chevrolet, GMC	P3 (L35) MTI (exc. KL5)
1997-99	Chevrolet, GMC	G2,3 (L35) MTI, NA4, ZK3

Engine-Specific Content: Oil Pump

Notes: Includes 21-PSI Oil Pressure Bypass Valve. When used in place of 12369214 for 98 and prior vehicles, flywheel 12557584 is required.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

12515469	262 CID New	<i>Heavy Duty</i>	4.3L
-----------------	-------------	-------------------	-------------

1985-89	Chevrolet, GMC	P4 Eng Dress Kit (LSA)*
1990-93	Chevrolet, GMC	CK2, P3 (LB4)(4.3Z), Emiss. above 8500lb. GVW (NA4)
1991-93	Chevrolet, GMC	G3 (LB4)(4.3A) Emiss. above 8500lb. GVW (NA4)

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, Oil Pump w/Screen, Torsional Damper, Valve Rocker Cover

Notes: *Effective with engine codes ADF, AJZ, FLX, and XDF.

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

88893272

262 CID New

4.3L

1996	Chevrolet, GMC	P3 (L35)(4.3W) CPI, MT1*
1996-2000	Chevrolet, GMC	CK1, S1 (L35)
1996-2000	Chevrolet, GMC	G1,2 (L35) M30, NA1 (exc. ZK3)

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, Oil Pump w/Screen, Torsional Damper, Valve Rocker Cover

Notes: When replacing a 1998 and prior Goodwrench engine (12532552), also use 1-12557587 flywheel for A. Trans or 1-12557586 for M. Trans. *Use together with 12557584 flywheel when replacing a Goodwrench engine (12532552) for P3 application.

Replaces: 12456496, 12532552

Replaced By: 89017329

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

88893274

262 CID New

4.3L

1996-2000	Chevrolet, GMC, Oldsmobile	T1 (L35)
1996-2000	Chevrolet, GMC	LM1 (L35)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, and Valve Rocker Covers

Notes: When replacing a 1998 and prior engine, also use 1-12557587 flywheel for A. Trans or 1-12557586 flywheel for M. Trans. Also needs Pilot Bearing 12557583.

Replaces: 12456499

Replaced By: 89017333

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

88893275

262 CID New

4.3L

1996-99

Chevrolet, GMC

S1 (LF6) M30, M50

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, and Valve Rocker Covers

Notes: When replacing a 1998 and prior engine, also use 1-12557587 flywheel for A. Trans or 1-12557586 flywheel for M. Trans.

Replaces: 12456500**Replaced By:**

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

88893276

262 CID New

4.3L

1996-99

Chevrolet, GMC

T1 (LF6)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, and Valve Rocker Covers

Notes: When replacing 1998 and prior (12532550), also use together with 12557587 Flywheel for automatic transmission or 12557586 for manual transmission usage.

Replaces: 12456501**Replaced By:**

INSTALLATION INSTRUCTIONS

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894118	262 CID New	4.3L
2001-02	Chevrolet, GMC	G2,3 (L35)(4.3W) MT1
<i>Engine-Specific Content:</i> Harmonic Balancer, Balance Shaft, Oil Pan, Front Cover, and Rocker Covers		
Replaces: 12570473		Replaced By: 89017322
INSTALLATION INSTRUCTIONS		
Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.		
<ul style="list-style-type: none"> • Replacement of oil related parts: If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler MUST BE REPLACED and the oil lines and remote filter adapter MUST BE REMOVED from the vehicle and thoroughly flushed or replaced. <u>Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.</u> • Intake Manifold: For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent MUST BE APPLIED to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders. • Front Covers: 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred. 		
CAUTION: The oil pump in this engine must be primed before starting engine. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

89017321	262 CID New	4.3L
2001-02	Chevrolet, GMC	CK1 (L35)(4.3W)
2001-02	Chevrolet, GMC	S1 (L35)(4.3W)
2001-02	Chevrolet, GMC	G1,2 (L35)(4.3W) M30
2002	Chevrolet, GMC	CK1 (LU3)
<i>Engine-Specific Content:</i> Light Duty - Shallow Oil Pan, Oil Pump, Front Cover, and Rocker Covers		
Replaces: 12570472, 88894116		Replaced By:
Notes: Swap Oil Pan from original engine or buy new (12555653) as required for Oil Level Switch.		
INSTALLATION INSTRUCTIONS		
Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.		
<ul style="list-style-type: none"> • Replacement of oil related parts: If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler MUST BE REPLACED and the oil lines and remote filter adapter MUST BE REMOVED from the vehicle and thoroughly flushed or replaced. <u>Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.</u> • Intake Manifold: For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent MUST BE APPLIED to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders. • Front Covers: 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred. 		
CAUTION: The oil pump in this engine must be primed before starting engine. <u>DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.</u>		

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017323

262 CID New

4.3L

2001	Chevrolet, GMC	LM1 (L35)
2001-02	Chevrolet, GMC	T1 (L35)
2001-03	Chevrolet, GMC	T1 (LG3) M30
2002	Chevrolet, GMC	LM1 (LU3)

Engine-Specific Content: Light Duty - Deep Oil Pan, Harmonic Balancer, Front Cover, and Rocker Covers

Replaces: 88894117, 12570474

Replaced By:

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

89017324

262 CID New

4.3L

2003-04	Chevrolet, GMC	S1 (LU3)
2003-04	Chevrolet, GMC	CK1 (LU3)
2003-04	Chevrolet, GMC	G1,2 (LU3)
2004	Chevrolet, GMC	R1 (LU3)
2005	Chevrolet, GMC	S1 (LU3) M50, M30

Engine-Specific Content: Oil Pump, Front Cover, and Rocker Covers

Replaces: 88984291, 12578698

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017325

262 CID New

4.3L

2003-04	Chevrolet, GMC	T1 (LU3)
2003-04	Chevrolet, GMC	LM1 (LU3) M30
2005	Chevrolet	ST1 (LU3) M30, ZR2

Engine-Specific Content: Oil Pump, Front Cover, and Rocker Covers

Replaces: 88984292, 12578699

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017331

262 CID New

4.3L

1997-99	Chevrolet, GMC	P3 (L35) MT1
1997-00	Chevrolet, GMC	G2,3 (L35) MT1, NA4 (exc. ZK3)

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, Oil Pump w/Screen, Torsional Damper, Valve Rocker Cover

Notes: When replacing a 1998 & prior GW engine (12369214), also use flywheel (12557584)

Replaces: 88893273, 12456497

Replaced By:

INSTALLATION INSTRUCTIONS

Instruct customer that the first service interval including an oil and filter change should be between 300 and 500 miles.

- **Replacement of oil related parts:** If the original engine failed either catastrophically or due to bearing failure, the engine oil cooler **MUST BE REPLACED** and the oil lines and remote filter adapter **MUST BE REMOVED** from the vehicle and thoroughly flushed or replaced. **Ingestion of fibers and grit from conditioning pads (i.e. Scotch Brite) is the number one cause of 4.3L engine failure.**
- **Intake Manifold:** For some engine assemblies (see service manual), sealer (part number 12346004) or equivalent **MUST BE APPLIED** to lower intake manifold bolts when installing the lower intake manifold. Failure to do so will usually result in increased oil consumption by allowing oil from the engine valley to be drawn into the intake manifold plenum. Since the plenum drain holes empty into cylinder #3 and #4, oil fouling will be greater on the spark plugs in these cylinders.
- **Front Covers:** 4.3 blocks with ten-bolt front cover provisions accept either ten-bolt metal covers or, after removing dowel pins, accept six-bolt plastic covers. On OBD II equipped engines, reluctor ring must also be transferred.

CAUTION: The oil pump in this engine must be primed before starting engine. **DAMAGE WILL RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

Straight 6 In-Line Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88984238

256 CID New

4.2L

2002-04

Chevrolet, GMC

ST1 (LL8)

Engine-Specific Content: Oil Filter, Oil Pan, Water Pump, Spark Plugs, and Flywheel

Notes: When used for 2002 application, the Spark Plugs, Knock Sensors and Oil Pan must be changed to 2002 parts.

Replaces: 88984108, 88894203

Replaced By: 89017685

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

V8 Engine Family Gasoline

APPLICATION, CONTENT & INSTALLATION PROCEDURES

This is a guide only. For specific questions, information and applications regarding any engine, please refer to the appropriate electronic GM Parts Catalog or contact PARTECH at 1-800-433-6961.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12567312	244 CID New	4.0L
1995-99	Oldsmobile	G (L47)(4.0C)
<i>Engine-Specific Content:</i> Drive Belt Tensioner, Front Cover, Oil Filter, Oil Level Sensors, Oil Press Sensor, Oil Pump w/Screen, and Water Pump w/Pulley		
Notes: Exc. Intake and Exhaust Manifold.		
Replaces: 12369567	Replaced By:	
INSTALLATION INSTRUCTIONS		
No special installation instructions are necessary. Please refer to the general installation procedure section of this book.		

88894238	244 CID New	4.0L
2001-02	Oldsmobile	G (L47)
<i>Engine-Specific Content:</i> Drive Belt Tensioner, Front Cover, Oil Filter, Oil Level Sensors, Oil Press Sensor, Oil Pump w/Screen, Water Pump w/Pulley, and Balancer		
Notes: Exc. Intake and Exhaust Manifold.		
Replaces: 12458125	Replaced By:	
INSTALLATION INSTRUCTIONS		
No special installation instructions are necessary. Please refer to the general installation procedure section of this book.		

88984255	244 CID New	4.0L
2003	Oldsmobile	G (L47)
Replaces: 12577028	Replaced By:	
INSTALLATION INSTRUCTIONS		
No special installation instructions are necessary. Please refer to the general installation procedure section of this book.		

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894191 262 CID New **4.3L**

1994-95 Chevrolet B (L99)(4.3W) (exc. KL5)

Engine-Specific Content: Oil Pan, Water Pump, Oil Pump, and Timing Chain

Notes: To be used for gasoline. Will not work for W/KL5. See partial engine 12524501 - 1994-96 (W/KL5).

Replaces: 12513025

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894192 262 CID New **4.3L**

1996 Chevrolet B (L99)(4.3W) (exc. KL5) Natural Gas

Engine-Specific Content: Oil Pan, Water Pump, Oil Pump, and Timing Chain

Notes: Does not include Intake Manifold, Exhaust Manifold, Flywheel, Ignition/Starter, or attaching parts. Will not work for W/KL5.

Replaces: 12533598

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12369568

280 CID New

4.6L

1993	Cadillac	E, V (L37)(4.6-9)
1994	Cadillac	K (L37)(4.6-9)

Engine-Specific Content: Cam & Crank Posn Sensors, Camshaft Covers, Crankshaft Balancer, Front Cover, Flywheel, Oil Filter w/Adapter, Oil Pan, Oil Pump, PCV Valve, Spark Plugs, Thermostat & Housing, and Water Pump w/Pulley

Notes:**Replaces:****Replaced By:** 12567315**INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12567313

280 CID New

4.6L

1995-99	Cadillac	K (L37)(4.6Y)
---------	----------	---------------

Engine-Specific Content: Cam & Crank Posn Sensors, Camshaft Covers, Crankshaft Balancer, Engine Oil Manifold, Front Cover, Flywheel, Oil Fill Cap, Oil Filter w/Adapter, Oil Level Indicator & Tube Assembly, Oil Level Sensor, Oil Pan, Oil Pump Suction Pipe, PCV Valve, Spark Plugs, Temperature Sensor, Thermostat & Housing, Water Pump w/Housing, and Water Pump w/Pulley

Notes: 1998 KS/KY models transfer or purchase Oil Level Indicator and Tube. 1995-97 models transfer or purchase Oil Filter Adapter (with oil clr ports). Early 1995 models, install fresh Air PCV Tube from group 1.762.

Replaces: 12369570, 12529514**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12567314

280 CID New

4.6L

1995-99	Cadillac	K (LD8)(4.6Y)
---------	----------	---------------

Engine-Specific Content: Cam & Crank Posn Sensors, Camshaft Covers, Crankshaft Balancer, Engine Oil, Front Cover, Flywheel, Oil Fill Cap, Oil Filter w/Adapter, Oil Pan, Oil Pump, and PCV Valve

Notes: On 1995-97 models, transfer or purchase Oil Filter Adapter (with oil clr ports). Early 1995 models, install fresh PCV Tube Assembly, part number 12552458.

Replaces: 12369571, 12529515**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12567316 280 CID New **4.6L**

1993 Cadillac E (LD8)(4.6Y)
1994 Cadillac K (LD8)(4.6Y)

Engine-Specific Content: Cam & Crank Posn Sensors, Camshaft Covers, Crankshaft Balancer, Front Cover, Flywheel, Oil Filter w/Adapter, Oil Pan, Oil Pump, PCV Valve, Spark Plugs, Thermostat & Housing, Water Pump w/Pulley, and Engine Oil

Replaces: 12369569, 12529512

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894239 280 CID New **4.6L**

2001-02 Cadillac K (L37)

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894240 280 CID New **4.6L**

2001-02 Cadillac K (LD8)

Notes: When used for Eldorado, swap dipstick tubes.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894249 280 CID Reman **4.6L**

2000 Cadillac K (LD8)

Replaces: 12458126

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894250 280 CID Reman **4.6L**

2000 Cadillac K (L37)

Notes: Engine assembly is used with and without V03 option. Comes with cooler adapter, remove for applications without V03.

Replaces: 12458127

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88984253 280 CID New **4.6L**

2003 Cadillac K (L37) Northstar

Replaces: 12577026

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88984254 280 CID New **4.6L**

2003 Cadillac K (LD8) Northstar

Replaces: 12577027

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017411 280 CID New **4.6L**

2004 Pontiac H (LD8)

2004 Cadillac K (LD8)

Replaces:

Replaced By: 89017626

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017446 280 CID New **4.6L**

2004 Cadillac Y (LH2)

Replaces: 89017394

Replaced By: 89017549

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017447 280 CID New **4.6L**

2004 Cadillac E (LH2)

Replaces: 89017393

Replaced By: 89017550

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12457703 292 CID New **4.8L**

1999 Chevrolet, GMC CK1 (LR4)(4.8V) M30

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Pan, and Oil Filter

Replaces: **Replaced By:** 88890536

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12457704 292 CID New **4.8L**

1999 Chevrolet, GMC CK1 (LR4) MG5

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Pan, and Oil Filter

Replaces: **Replaced By:** 88890536

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88893289 292 CID New **4.8L**

2000 Chevrolet, GMC CK1 (LR4) M30

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, Water Pump and Rocker Covers

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88893290 292 CID New **4.8L**

2000 Chevrolet, GMC CK (LR4) MG5

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, Water Pump and Rocker Covers

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017353 292 CID New **4.8L**

2000-04 Chevrolet, GMC CK1 (LR4)
2003-04 Chevrolet, GMC G2,3 (LR4) MT1

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, Water Pump and Rocker Covers

Replaces: 88894060, 88893290, 88893289,
88894257, 88984274 **Replaced By:** 89017656

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12518296

305 CID New

5.0L

1988-92	Chevrolet, Pontiac	F (L03)(5.0H)
1989-93	Chevrolet	B (L03)(5.0H)
1989-92	Buick	B (L03)(5.0H)
1991-92	Oldsmobile	B (L03)(5.0H)
1991-92	Cadillac	D (L03)(5.0H)

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, and Valve Rocker Cover

INSTALLATION INSTRUCTIONS

- This engine is built with 1993 production components. When servicing engine, use 1993 service parts.
- For "D" and "F" car applications, remove oil pan and replace with pan from replaced engine or order oil pan kit, part number 12518044.
- For applications without oil level sensors, plug hole using plug, part number 3448834, and T/W thread sealer, part number 12345493.
- Engine built after 04/13/94 have roller timing chains. For second service, sprocket part numbers 12552129 and 14088784, chain part number 14088783 and bolt part number 9417950 must be used. Engines built with link timing chain must use camshaft sprocket part number 10168441, crankshaft sprocket part number 10128346, chain part number 10128485 and bolt part number 3874878.
- This engine is built to production point of build torque specifications, and loss of some bolt torque is normal. It is not necessary to retorque any bolts.

12518298

305 CID New

5.0L

1987-95	Chevrolet, GMC	G1,2 (L03)(5.0H)
1987	Chevrolet, GMC	R1,2 V1 (L03)(5.0H)
1988-95	Chevrolet, GMC	CK1,2 (L03)(5.0H)

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, and Valve Rocker Cover

Replaces: 10181385

Replaced By:

INSTALLATION INSTRUCTIONS

- This engine is built with 1993 production components. When servicing engine, use 1993 service parts.
- Install clutch pilot bearing, part number 03752487, for manual transmission applications.
- This engine is built with cylinder heads that have counter-bored inlet manifold attaching end holes (for piloted inlet manifold side gaskets) that require 1/4" longer fasteners.
- On 1987-90 models, the following parts are required:

R.H. Front	09439918*
R.H. Rear	15538420*
L.H. Front	10108663
L.H. Rear	09439918*

*Use sealer part number 1052080. Use inlet manifold gasket kit part number 12506365.
- On 1987 RV10 & R20 models: Remove and discard front cover. Install front cover from original engine or obtain front cover assembly part number 10089669. Install torsional damper from original engine or obtain torsional damper part number 10066046.
- This engine incorporates current valve rocker cover. It may be necessary to use covers from original engine.
- This engine is built to production point of build torque specifications, and loss of some bolt torque is normal. It is not necessary to retorque any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12530284

305 CID New

5.0L

1996-99	Chevrolet, GMC	CK1,2 (L30)(5.0M) MG5, M30
1996-2002	Chevrolet, GMC	G1,2 (L30)(5.0M) M30

Engine-Specific Content: Front Cover, Oil Fill Cap, Oil Pan, and Valve Rocker Cover

Notes: For 2001 G-van application, service engine block contains English threads. When used for 2001 vehicles, must also use 2000 MY Starter/Trans/Eng mounting bolts.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

22538277

307 CID Reman

5.0L

1986-90	Cadillac	D (LG8)(5.0-9) B05
1986-87	Oldsmobile	G (LG8)(5.0-9)

Engine-Specific Content: Crankshaft, Inj Pump Drive, Oil Pump w/Screen, Conn. Rod and Bearings, Pistons, Camshaft, Cylinder Heads, Valves, Lifters, Push Rods, and Timing Chain

Notes: Engine does not include Water Pump, Intake or Exhaust Manifold, Flywheel, Front Cover or Oil Pan.

Replaces: 22536528

Replaced By:

INSTALLATION INSTRUCTIONS

- Oil Pump Screen Height: The oil pump pickup screen has a possibility of being moved out of location during normal handling of the engine. Prior to reinstallation of the oil pan, check the location of the screen.
- Oil Pump: On all "E" or "K" models, remove the oil pump from the old engine. If the engine being replaced has high mileage, it is suggested you purchase a new oil pump. If it is low mileage and the oil pump worked well, transfer the pump from the old engine. Failure to change the pump will result in oil starvation because of the pickup screen height.
- This remanufactured engine contains the following materials for your use:
 - Valve cover labels - after installation in the car, affix to each valve cover
 - Bill of lading for core return - fill out and supply to carrier when core is shipped

GOODWRENCH SERVICE REPLACEMENT ENGINES

12457705 323 CID New **5.3L**

1999 Chevrolet, GMC CK1,2 (LM7)(5.3T) M30

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Pan, Oil Filter, and Valve Rocker Covers

Replaces: **Replaced By:** 88890540

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88893291 323 CID New **5.3L**

2000 Chevrolet, GMC CK1 (LM7)(5.3T) MFI

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Pan, Oil Filter, and Valve Rocker Covers

Replaces: 12565185 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017354 323 CID New **5.3L**

2001	Chevrolet, GMC	CK1,2 (LM7)
2002	Chevrolet, GMC	C1,2 K1 (LM7)
2002-04	Chevrolet, GMC	CK1 (L59) M30
2003-04	Chevrolet, GMC	GH 1,2 (LM7) M30, NC8, NF4, NT9
2003-04	Chevrolet, GMC	CK1 (LM7) M30
2004	Chevrolet, GMC	CK1 (LM7) M33

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, Water Pump, and Rocker Covers

Replaces: 88984275, 88894061, 88894258 **Replaced By:** 89017657

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017355 323 CID New **5.3L**

2003-04 Chevrolet, GMC ST1 (LM4) M30

Engine-Specific Content: Oil Pump, Front Cover, Water Pump, and Rocker Covers

Replaces: 88984276, 12577732 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

10067353

350 CID New

5.7L

1983-85	Chevrolet	B (LM1)(350-6) SEO
1979-84	Chevrolet, GMC	CK1 (06)(LT9)(350M) (LS9)(350L)
1979-85	Chevrolet, GMC	K1 (LS9)(350L)
1980-85	Chevrolet, GMC	G1,2,3 (LT9)(350M) (LS9)(350L) (LM1)(350L)
1981-82	Chevrolet, GMC	CK1 (03)(LM1)(350L)
1985	Chevrolet, GMC	CK1(06) G1 (LS9)(350L)

Engine-Specific Content: Front Cover, Oil Pan, and Valve Covers

Notes: Refer to Service Catalog for detailed usage requirements.

Replaces: 14009800

Replaced By:

INSTALLATION INSTRUCTIONS

- Part number 10067353 Goodwrench 5.7 Liter (350 C.I.D.) V8 engine is to be used on 1973 through 1985 Chevrolet passenger cars (also 1977-79 Buick, Oldsmobile, and Pontiac) with VIN "K" or "L" and 1973 through 1985 Chevrolet-GMC light duty truck with VIN "Y" or "L".
- Not to be used for Taxi, Police, High-Performance, LPG or Low Compression Export applications; also, 1974 California passenger car.
- Remove any paint from cylinder block to clutch housing or transmission mounting surface and crankshaft before installing engine.
- Check engine restrictor at center of inlet manifold side gaskets from replaced engine and procure one of the following units:

Unit Part Number	Restrictor
10174954	L.H. open, R.H. 5/8"
00345195	Both 5/8"
10147994	Both open
- Two timing pointers are provided with this assembly. Determine and install correct pointer or install front cover assembly from replaced engine.
- Some models may require R.H. cylinder head be drilled and tapped (3/8"-16") for exhaust manifold rear bolt attachment.
- Plug either L.H. or R.H. side of cylinder block with plug furnished. Plug side opposite of dipstick location.
- This engine is built to production point of build torque specifications, and loss of some bolt torque is normal. It is not necessary to retorquer any bolts.

12455109

350 CID New

5.7L

1997-98	Chevrolet	Y (LS1)(5.7G)
---------	-----------	---------------

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, Intake Manifold, Fuel Rail, and Water Pump

Replaces:

Replaced By: 88894382

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12457660	350 CID New	5.7L
1999	Chevrolet	Y (LS1)(5.7G)
<i>Engine-Specific Content:</i> Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, Intake Manifold, Fuel Rail, and Water Pump		
Replaces:		Replaced By: 88890543
INSTALLATION INSTRUCTIONS		
No special installation instructions are necessary. Please refer to the general installation procedure section of this book.		

12513151	350 CID New	5.7L
1991-93	Chevrolet	B (L05)(5.7K), Exc. SEO Police Car (9C1)
1992-93	Buick	B (L05)(5.7K)
1991-93	Cadillac	D (L05)(5.7K)
1992	Oldsmobile	B (L05)(5.7K)
<i>Engine-Specific Content:</i> Crankshaft Hub, Oil Pan, and Valve Rocker Cover		
INSTALLATION INSTRUCTIONS		
<ul style="list-style-type: none"> Part number 12513151 5.7 Liter engine is built with 1993 model year designed oil pan (no rail bead) and oil pan gasket. When servicing this engine, it is required that replacement parts be of that same type of design. On "D" car models 1992 & prior, remove oil pan and replace with original or with new part number 12518044. Engines built after 04/13/94 have roller timing chains. For second service, use sprocket part number 12552129 and part number 14088784, chain part number 14088783 and bolt part number 9417950. Engine built with link timing chain must use camshaft sprocket part number 10168441, crankshaft sprocket part number 10128346, chain part number 10128485 and bolt part number 3874878. This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts. 		

GOODWRENCH SERVICE REPLACEMENT ENGINES

12520270

350 CID New

5.7L

1987-94	Chevrolet, GMC	G3 (L05)(5.7K) Emis. Sys (above 8500lb. GVW) NA4
1987-90	Chevrolet, GMC	P2,3 (L05)(5.7K) Emis. Sys (above 8500lb. GVW) NA4
1987-91	Chevrolet, GMC	RV2,3 (L05)(5.7K) Emis. Sys (above 8500lb. GVW) NA4
1988-95	Chevrolet, GMC	CK2,3 (L05)(5.7K) Emis. Sys (above 8500lb. GVW) NA4
1991-96	Chevrolet, GMC	P3 (L05)(5.7K)
1994-96	Chevrolet, GMC	G3 (L05)(5.7K) MT1 (exc. KL5, 5Z1, 9C2, NM8)
1994-96	Chevrolet, GMC	G3 (L05)(5.7K) NM8, MT1 (exc. 9C2)
1994-96	Chevrolet, GMC	G3 (L05)(5.7K) 5Z1 (exc. 9C2, NM8)
1995	Chevrolet, GMC	G3 (L05)(5.7K) MT1, 9C2, 5Z1 (exc. NM8)

Engine-Specific Content: Front Cover, Oil Pan, Torsional Damper, and Valve Rocker Cover

Replaces: 12509657

Replaced By:

INSTALLATION INSTRUCTIONS

- Part number 12520270 5.7 Goodwrench 5.7 Liter engine is built with 1993 model year designed oil pan (no rail bead), oil pan gasket, and oil pump assembly. When servicing this engine, it is required that replacement parts be of the same type and design.
- This engine is built with current-production valve rocker covers. It may be necessary to use cover from replaced engine.
- On models with a 5-Quart Oil Pan, remove oil pan and oil pump assembly. Replace with original or new oil pan assembly part number 12518043, oil pump assembly part number 10168529, and screen oil part number 10166159.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorquer any bolts.

12530282

350 CID New

5.7L

1999-2000	Chevrolet, GMC	CK1 (L31) M30 (exc. NM8)
1996-98	Chevrolet, GMC	CK1,2 (L31)(5.7R) M50, M30 (exc. NM8)
1996-2002	Chevrolet, GMC	G1,2 (L31)(5.7R) M30

Engine-Specific Content: Crankshaft Hub, Front Cover, Oil Pan, and Valve Rocker Cover

Notes: For 2001 G-van application, service engine block contains English threads. May require Valve Covers to be transferred from original engine for some applications

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12530283

350 CID New

5.7L

1996-2000	Chevrolet, GMC	CK2,3 (L31) MT1 (exc. NM8, KL5)
1996-2000	Chevrolet, GMC	CK2,3 (L31)(5.7R) MW3 (exc. NM8)
1996-2002	Chevrolet, GMC	G2,3 (L31)(5.7R) MT1
1996-99	Chevrolet, GMC	P3 (L31)(5.7R) MW3, MT1 (exc. NM8, KL5)

Engine-Specific Content: Crankshaft Hub, Front Cover, Oil Pan, and Valve Rocker Covers

Notes: For 2001 G-van applications, service engine block contains English threads. When used for 2001 and 2002 vehicles, must also use 2000 MY Starter/Trans/Eng mounting bolts.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12534776 **5.7L**
350 CID New

1996 Chevrolet Y (LT4)

Engine-Specific Content: Front Cover, Oil Pan, Oil Pump w/Shaft and Cover, Water Pump w/Shaft and Cover

Notes: Does not include Inlet Manifold, Exhaust Manifold, Starter, Flywheel, Water Pump, Ignition or Attaching Parts

Replaces: **Replaced By:** 88894198

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12568758 **5.7L**
350 CID New

1987-92	Chevrolet, GMC	G1,2,3 (L05)(5.7K) MD8
1987	Chevrolet, GMC	RV1,2 (L05)(5.7K) Emis. Sys (under 8500lb. GVW) NA1
1988	Chevrolet, GMC	CK1,2 (L05)(5.7K)
1988-91	Chevrolet, GMC	RV1 (L05)(5.7K)
1989-95	Chevrolet, GMC	CK1,2 (L05)(5.7K) Emis. Sys (under 8500lb. GVW) NA1
1993-94	Chevrolet, GMC	G1,2,3 (L05)(5.7K) Emis. Sys (under 8500lb. GVW) NA1
1995	Chevrolet, GMC	G2,3 (L05)(5.7K) M30 Emis. Sys (under 8500lb. GVW) NA1

Engine-Specific Content: Front Cover and Pointer, Oil Pan, Torsional Damper, and Valve Rocker Covers

Replaces: 12520268 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12568759 **5.7L**
350 CID New

1986	Chevrolet, GMC	CK1 (LS9)(350L)
1986	Chevrolet, GMC	G1,2,3 (LS9)(350L)

Engine-Specific Content: Front Cover and Valve Rocker Covers

Replaces: 10048971 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12569010 **5.7L**
350 CID New

1996-2003 Chevrolet, GMC W4 (L31)

Engine-Specific Content: Oil Pan

Notes: For 2001 application, must use 2000 transmission/engine and starter mounting bolts. Service engine block has English mounting threads.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12569068 350 CID New **5.7L**

1993-95 Chevrolet, GMC W4 (L05)
2000 Chevrolet, GMC W4

Engine-Specific Content: Oil Pan

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88893286 350 CID New **5.7L**

2000 Chevrolet Y (LS1)(5.7G) MFI Alum

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, Intake Manifold, Fuel Rail, and Water Pump

Replaces: **Replaced By:** 88890544

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88893287 350 CID New **5.7L**

1999-00 Chevrolet, Pontiac F (LS1)(5.7G)

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, Intake Manifold, Fuel Rail, and Water Pump

Replaces: 12457659 **Replaced By:** 88890545

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894086 350 CID New **5.7L**

1998 Chevrolet, Pontiac F (LS1)(5.7G)

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, Intake Manifold, Fuel Rail, and Water Pump

Replaces: 12455110 **Replaced By:** 88894386

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894193 350 CID New **5.7L**

1994-95 Chevrolet, Buick B (LT1)(5.7P)
1994-95 Cadillac B (LT1)(5.7P)

Engine-Specific Content: Crankshaft Hub and Valve Rocker Cover

Replaces: 12513026 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894194 **5.7L**
 350 CID New

1996	Chevrolet, Buick	B (LT1)(5.7P)
1996	Cadillac	B (LT1)(5.7P)

Engine-Specific Content: Front Cover, Oil Pan, Oil Pump w/Shaft and Cover, Water Pump w/Shaft and Cover

Notes: Does not include Inlet Manifold, Exhaust Manifold, Starter, Flywheel, Ignition, or Attaching Parts

Replaces: 12533599 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894195 **5.7L**
 350 CID New

1995	Chevrolet, Pontiac	F (LT1)(5.7P)
1995	Chevrolet	Y (LT1)(5.7P)

Engine-Specific Content: Crankshaft Hub, Front Cover, Oil Pan, and Valve Rocker Cover

Replaces: 12524896 **Replaced By:**

INSTALLATION INSTRUCTIONS

- On "Y" car applications, valve covers, oil pan, and oil pump screen must be replaced with original parts or purchased new as follows:

<u>Valve Covers (w/gasket)</u>	<u>Valve Cover Bolts</u>	<u>Oil Pump Screen</u>	<u>Oil Pan Kit/Pan Gasket</u>
12552321 LH	10108675	12550106	10242242
12552322 RH	10108674		10108676
- If there is insufficient 'press' after installing the oil pump screen, replace oil pump with part number 12555283.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorque any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894196

350 CID New

5.7L

1993-94	Chevrolet, Pontiac	F (LT1)(5.7P)
1992-94	Chevrolet	Y (LT1)(5.7P)

Engine-Specific Content: Crankshaft Hub, Front Cover, Oil Pan, and Valve Rocker Cover

Replaces: 12523000

Replaced By:

INSTALLATION INSTRUCTIONS

- On "Y" car applications, valve covers, oil pan, and oil pump screen must be replaced with original parts or purchased new as follows:

<u>Year</u>	<u>Valve Covers</u>	<u>Valve Cover Bolts</u>	<u>Oil Pump Screen</u>	<u>Oil Pan Kit/Pan Gasket</u>
1992	N/A LH 10055782 RH	10088165	12550106	10242242 10108676
1993	12552321 LH* 12552322 RH*	10108675 10108674	12550106	10242242 10108676
1994	12552321 LH* 12552322 RH*	10108675 10108674	12550106	10242242 10108676

*Includes valve cover gasket

- If there is insufficient 'press' after installing the oil pump screen, replace oil pump with part number 12555283.
- This engine is built with 1994 production parts. When servicing the cylinder head and valve train, use 1994 components.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorquer any bolts.

88894197

350 CID New

5.7L

1996-97	Chevrolet, Pontiac	F (LT1)(5.7P)
1996	Chevrolet	Y (LT1)(5.7P)

Engine-Specific Content: Front Cover, Oil Pan, Oil Pump w/Shaft and Cover, Water Pump w/Shaft and Cover

Notes: Does not include Inlet Manifold, Exhaust Manifold, Starter, Flywheel, Water Pump, Ignition or Attaching Parts

Replaces: 12533597

Replaced By:

INSTALLATION INSTRUCTIONS

- On "Y" car applications, valve covers, oil pan, and oil pump screen must be replaced with original parts or purchased new as follows:

<u>Valve Covers (w/gasket)</u>	<u>Valve Cover Bolts</u>	<u>Oil Pump Screen</u>	<u>Oil Pan Kit/Pan Gasket</u>
12552321 LH	10108675	12550106	10242242
12552322 RH	10108674		10108676

- If there is insufficient 'press' after installing the oil pump screen, replace oil pump with part number 12555283.
- This engine is built to production point of build torque specifications, and loss of some torque is normal. It is not necessary to retorquer any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894384 350 CID New **5.7L**

2001 Chevrolet Y (LS6)

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, Water Pump, and Rocker Covers

Replaces: 88894057

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017349 350 CID New **5.7L**

2003-04 Chevrolet Y (LS6)

Engine-Specific Content: Harmonic Balancer, Oil Pan, Oil Pump, Front Cover, Water Pump, and Rocker Covers

Replaces: 88984272, 88894254

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017352 350 CID New **5.7L**

2004 Pontiac 8V (LS1) GH4

Engine-Specific Content: Harmonic Balancer, Oil Pan, Oil Pump, Front Cover, Water Pump, and Rocker Covers

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017548 350 CID New **5.7L**

2001-04 Chevrolet Y (LS1)

2001-02 Chevrolet, Pontiac F (LS1)

Engine-Specific Content: Harmonic Balancer, Oil Pan, Oil Pump, Front Cover, Water Pump, and Rocker Covers

Replaces: 89017348, 89017384, 89017275,
88984271

Replaced By:

Notes: 2001 applications may require rocker arm covers to be transferred from original engine.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017653

350 CID New

5.7L

2005

Cadillac

D (LS6)

Engine-Specific Content: Harmonic Balancer, Oil Pan, Oil Pump, Front Cover, Water Pump, and Rocker Covers

Replaces: 89017350**Replaced By:****INSTALLATION INSTRUCTIONS**

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12339198

366 CID Reman

6.0L

1985-90	Chevrolet, GMC	B6, C6,7, P6, S7 (L86)(366)
1988-90	Chevrolet, GMC	C6,7 (LS0)(366) NA5
1988-90	Chevrolet, GMC	B6 (LS0)(L86)
1990	Chevrolet, GMC	C5,6,7 (LS0)(366)

Notes: First design 1995 Head Casting is 14081052 (except Columbia)(for 1st design, see 12339197).

INSTALLATION INSTRUCTIONS

- This Chevrolet Mark IV engine has been remanufactured subsequent to the model year of the vehicle and incorporates design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Parts and Accessories information bulletins and Chevrolet dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.
- Use new seals and gaskets. Install the supplied oil pump and transfer all necessary components including oil pan, and valve covers to the replacement engine. Thoroughly clean all old parts to avoid possible contamination.
- 1990 trucks have an ESC sensor. It may be necessary to tap the oil tube-mounting hole with 1/4-18 dry-seal tap to install the sensor on the replacement engine. Use a thread sealer to prevent coolant leaks.
- On certain models with shallow oil pan, a new oil pump assembly, part number 14067529, with shorter pick-up tube must be installed in place of the pump supplied with this engine.
- Attach two Goodwrench engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting the engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Use 6 quarts of A.P.I. Starburst certified oil in the viscosity suitable for your climate conditions. **DAMAGE COULD RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED PROPERLY.**

12457706

366 CID New

6.0L

1999-2000	Chevrolet, GMC	CK2 (LQ4)(6.0U) MFI (MT1)
-----------	----------------	---------------------------

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, and Valve Covers

Replaces:
Replaced By: 88890542

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12465229 366 CID New *Electric Fuel Pump Application Only* **6.0L**

1986-89	Chevrolet, GMC	M4,5,6 (L86) MF1 (exc. oil cooler KPS, air comp application)
1986-90	Chevrolet, GMC	M4,5,6 (L86) BQG, KPS (exc. BQG)(with kit #15662081)
1986-90	Chevrolet, GMC	M4,5,6 (L86) MF1, MT9, KPS (exc. BQG)(with kit #15662081)
1986-89	Chevrolet, GMC	C6,7 (L86) (exc. KPS) (with M.T. and #15667482)
1986-89	Chevrolet, GMC	C6,7 (L86) KPS (with M.T. and # 15662081)(exc. air comp application)
1986-89	Chevrolet, GMC	C6,7 (L86) ME4, ME6 (exc. KPS)
1986-89	Chevrolet, GMC	C6,7 (L86) MF1 (exc. KPS) (w/IMF9)
1986-90	Chevrolet, GMC	C6,7 (L86) ME4, ME6 (with kit #15637482)(exc. air comp application)
1986-90	Chevrolet, GMC	C6,7 (L86) ME4, ME6, KPS (with kit #15662081)(exc. air comp application)
1986-90	Chevrolet, GMC	C6,7 (L86) MF1, KPS (exc. air comp application)
1989-90	Chevrolet, GMC	C6,7 (LS0) MF1 (exc. KPS)(with air comp kit #15637482)
1989-90	Chevrolet, GMC	C6,7 (LS0) M.T. (air comp #15637482)
1989-90	Chevrolet, GMC	C6,7 (LS0) KPS (exc. KPS)
1989-90	Chevrolet, GMC	B6 (LS0) (exc. KPS) (M.T., air comp #15637482)
1989-90	Chevrolet, GMC	B6 (L86) 366 (LS0) MF1 (exc. oil cooler KPS, air comp application)
1990	Chevrolet, GMC	C5,6,7 (LS0) (exc. KPS)
1991	Chevrolet, GMC	B6 (LS0) 366
1991-98	Chevrolet, GMC	C6,7 (LS0)
1992-96	Chevrolet, GMC	P6 (LS0)
1993-98	Chevrolet, GMC	B7 (LS0)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, Valve Rocker Covers

Notes: *Electric Fuel Pump Application Only.* When replacing engines with 8-inch dampener, must also use 1-12529747 water pump.

Replaces: 12530366

Replaced By:

INSTALLATION INSTRUCTIONS

NOTICE: When using this engine to replace 1990 and prior applications, the following kits are required:

<u>Retrofit Kit #</u>	<u>Model</u>	<u>Year</u>	<u>Restrictions</u>
12531193	C6,7	1991-98	
12531193	B7	1997-98	
12531193	P6	1992-96	
15637113	C6,7	1989-90	
15637113	B6	1989-90	
15637114	C6,7	1989-90	
15637114	C5,6,7	1990	
15637114	B6	1989-90	
15637115	C6,7	1989-90	
15662928	M4,5,6	1986-90	
15662928	C6,7	1986-89	
15662943	M4,5,6	1986-90	
15662943	C6,7	1986-89	
15662944	C6,7	1986-89	

GOODWRENCH SERVICE REPLACEMENT ENGINES

88890535 366 CID New *Mechanical Fuel Pump Application Only* **6.0L**

1986-89	Chevrolet, GMC	M4,5,6 (L86) (exc. KPS) w/M.T.
1986-89	Chevrolet, GMC	M4,5,6 (L86) MF1 (exc. oil cooler KPS, air comp application)
1986-90	Chevrolet, GMC	M4,5,6 (L86) BQG, KPS (exc. BQG) (with kit #15662081)
1986-90	Chevrolet, GMC	M4,5,6 (L86) MFI, KPS (exc. BQG) (with kit #15662081) (IMT9)
1986-90	Chevrolet, GMC	C6,7 (L86) ME4, ME6 (exc. oil cooler application) (with kit 15637482)
1986-90	Chevrolet, GMC	C6,7 (L86) ME4, ME6, KPS (exc. air comp application) (with kit 15662081)
1986-90	Chevrolet, GMC	C6,7 (L86) MF1 (exc. KPS) (with kit #15637482)
1986-90	Chevrolet, GMC	C6,7 (L86) MF1, KPS (exc. air comp application)
1986-90	Chevrolet, GMC	C6,7 (L86) (exc. KPS) (with M.T. and kit #15667482)
1986-89	Chevrolet, GMC	C6,7 (L86) KPS (exc. air comp application) (with M.T. and kit #15662081)
1986-90	Chevrolet, GMC	C6,7 (L86) ME4, ME6 (exc. KPS)
1986-90	Chevrolet, GMC	C6,7 (L86) MF1 (exc. KPS)
1989-90	Chevrolet, GMC	B6 (LS0) (exc. KPS) (M.T., air comp #15637482)
1989-90	Chevrolet, GMC	B6 (L86) 366 (LS0) M.T. (exc. oil cooler KPS, air comp application)
1989-90	Chevrolet, GMC	B6 (L86) 366 (LS0) MF1 (exc. oil cooler KPS, air comp application)
1989-90	Chevrolet, GMC	C6,7 (LS0) KPS (exc. KPS)
1990	Chevrolet, GMC	C5,6,7 (LS0) (exc. KPS)
1991	Chevrolet, GMC	B6 (LS0) 366
1991-98	Chevrolet, GMC	C6,7 (LS0)
1992-96	Chevrolet, GMC	P6 (LS0)
1993-98	Chevrolet, GMC	B7 (LS0)
1997-98	Chevrolet, GMC	F6,7 (LS0)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, Valve Rocker Covers

Notes: *Mechanical Fuel Pump Application Only.* When replacing engines with 8-inch dampener, must also use 1-12529747 water pump.

Replaces: 12530366

Replaced By:

INSTALLATION INSTRUCTIONS

NOTICE: When using this engine to replace 1990 and prior applications, the following kits are required:

<u>Retrofit Kit #</u>	<u>Model</u>	<u>Year</u>	<u>Restrictions</u>
12531193	C6,7	1991-98	
12531193	B7	1997-98	
12531193	P6	1992-96	
15637113	C6,7	1989-90	
15637113	B6	1987-90	
15637114	C6,7	1989-90	
15637114	C5	1990	
15637115	C6,7	1989-90	
15637115	B6	1989-90	
15662928	M4,5,6	1986-90	
15662928	C6,7	1986-89	
15662943	M4,5,6	1986-90	
15662943	C6,7	1986-89	
15662944	C6,7	1986-89	

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017356 **6.0L**
 366 CID New

2003-04	Chevrolet, GMC	CK2,3 (LQ4) MW3
2001-04	Chevrolet, GMC	CK1,2,3 (LQ4) MT1 (exc. KL5)
2003-04	Chevrolet, GMC	K1 (LQ4) M32
2003-04	Chevrolet, GMC	G2,3 (LQ4) MT1 (exc. KL5)
2003-04	Hummer	N 257 (LQ4) M32, NC1, NT9

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, and Water Pump

Replaces: 88984277, 88894062, 88894259 **Replaced By:** 89017659

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017357 **6.0L**
 366 CID New

2001	Chevrolet, GMC	K1 (LQ4) KL5
2001	Chevrolet, GMC	CK2,3 (LQ4) KL5
2002-04	Chevrolet, GMC	CK1,2,3 (LQ4) MT1, KL5
2003-04	Chevrolet, GMC	G2,3 (LQ4) MT1, KL5
2003-04	Chevrolet, GMC	W4 (LQ4)

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, and Valve Covers

Replaces: 89017358, 88984278, 88894260, 88894063 **Replaced By:** 89017660

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017358 **6.0L**
 366 CID New

2003-04	Chevrolet, GMC	W4 (LQ4)
---------	----------------	----------

Engine-Specific Content: Front Cover, Harmonic Balancer, Oil Filter, Oil Pan, and Valve Covers

Replaces: 88984282 **Replaced By:** 89017357

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017359 **6.0L**
 366 CID New

2002-03	Chevrolet, GMC	K1 (LQ9)
2004	Chevrolet, GMC	CK1 (LQ9) M32

Engine-Specific Content: Harmonic Balancer, Oil Pan, Front Cover, and Water Pump

Replaces: 12573037, 88894261, 88984279 **Replaced By:** 89017661

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.



GOODWRENCH SERVICE REPLACEMENT ENGINES

89017654

366 CID New

6.0L

2005

Chevrolet

Y (LS2)

Engine-Specific Content: Oil Pan and Front Cover

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12339196

427 CID Reman

7.0L

1985-90	Chevrolet, GMC	C7 (L43)
1988-90	Chevrolet, GMC	C6,7 (L43) NA5 (427)
1990	Chevrolet, GMC	C5,6,7 (LR0)
1990	Chevrolet, GMC	P6 (LR0)

Notes: Head casting is 14081052 (except Columbia)(for 1st design, see 12339195).

INSTALLATION INSTRUCTIONS

- This Chevrolet Mark IV engine has been remanufactured subsequent to the model year of the vehicle and incorporates design refinements not included in original service information (i.e., 1982 engines may incorporate design features normally associated with 1987 models). If future service is required for this engine, consult GM Parts catalogs, GM Part and Accessories information bulletins, and Chevrolet dealer service bulletins for proper service parts and service procedures necessary to accommodate these revisions.
- Use new seals and gaskets. Install the supplied oil pump and transfer all necessary components including oil pan and valve covers to the replacement engine. Thoroughly clean all old parts to avoid possible contamination.
- 1990 trucks have an ESC sensor. It may be necessary to tap the oil-tube mounting hole with 1/4-18 dry-seal tap to install the sensor on the replacement engine. Use a thread sealer to prevent coolant leaks.
- On certain models with shallow oil pan, a new oil pump assembly, part number 14067529, with shorter pickup tube must be installed in place of the pump supplied with this engine.
- Attach two Goodwrench engine decals (enclosed in instructions envelope) to clean valve covers.

CAUTION: The oil pump in this engine must be primed before starting engine. Refer to vehicle service chassis manual for proper priming procedures. Also, check engine oil level before starting engine. Use 6 quarts of Starburst certified oil in the viscosity suitable for your climate conditions. **DAMAGE COULD RESULT IF ENGINE IS STARTED WITHOUT OIL OR IF OIL PUMP IS NOT PRIMED.**

12530427

427 CID New

7.0L

1995	Chevrolet, GMC	C6,7 (LR0)
1995-96	Chevrolet, GMC	P6 (LR0) MF1
1995-98	Chevrolet, GMC	B7 (LR0) MF1, ENN
1996	Chevrolet, GMC	C6,7 (LR0) MWW, MWX (exc. ENN)
1996-98	Chevrolet, GMC	C6,7 (LR0) ME4, ME6, MF1, MT9, MWX

Notes: 6-bolt Front Cover

Replaces: 12524680

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

12532427

427 CID New

7.0L

1986-90	Chevrolet, GMC	C6,7 (L43) MFI, MT9
1991-98	Chevrolet, GMC	C6,7 (LR0) ME4, ME6, JE4
1992-96	Chevrolet, GMC	P6 (LR0)
1994-96	Chevrolet, GMC	B7 (LR0)

Notes: Rocker cover may have to be swapped for some applications. See catalog for retrofit and RPO specific information.

Replaces: 12524683, 10181240

Replaced By:

INSTALLATION INSTRUCTIONS

Part number 12532427, Goodwrench 7.0 Liter engine assembly, has been developed as a service replacement engine for 1986-1994 medium duty truck 427 C.I.D. engine applications.

NOTICE: When using this engine to replace 1990 and prior applications, the following kits are required:

<u>Retrofit Kit #</u>	<u>Model</u>	<u>Year</u>	<u>Restrictions</u>
15637119*	C7	1990	LR0 w/M.T.
15637120*	C7	1990	LR0 w/MF1
15637121*	C7	1990	LR0 w/ME4, ME6 Trans
15662931	C7	1986-89	L43 w/M.T.
15662932	C7	1986-89	L43 w/MF1, MT9, IMT9
15662933	C7	1986-89	L43 w/ME4, ME6
15662932	P6	1986-90	L43 w/MF1, MT9, IMT9

**indicates kit includes oil cooling.*

<u>Oil Cooling Kit</u>	<u>Model</u>	<u>Year</u>	<u>Restrictions</u>
15662081	C6,7	1986-90	LR0, L43 w/oil cooling
15662081	P6	1986-90	L43 w/KPS (exc. BQG)
15662082	P6	1986-90	L43 w/KPS and BQG

<u>Air Compressor Kit</u>	<u>Model</u>	<u>Year</u>	<u>Restrictions</u>
15637482	P6	1986-90	L43
15637482	C6,7	1986-90	L43
15637483	C6,7	1990	427 LR0 VIN "H"

NOTICE: This engine comes equipped with an 8" front damper. On 1991 through 1994 trucks, you must purchase a new water pump and lower radiator hose. For 1990 and prior, you must replace the water pump with part number 12529747 to clear the 8" damper.

<u>Year</u>	<u>Water Pump</u>	<u>Hoses</u>	<u>Usage</u>
1991-94	12529192	15967462	Exc. MWE
1991-94	12529192	15967464	w/MWE
1986-90	12529747		

GOODWRENCH SERVICE REPLACEMENT ENGINES

12339193

454 CID Reman

7.4L

1980-86	Chevrolet, GMC	C2 CK3 (LE8)(7.4W)
1987-90	Chevrolet, GMC	R2,3 (L19)(7.4N)
1987-89	Chevrolet, GMC	RV2,3 (LE8)(7.4W)
1987-88	Chevrolet, GMC	V3 (L19)(7.4N)
1988-90	Chevrolet, GMC	CK3 G3 (L19)(7.4N)
1990	Chevrolet, GMC	C1 (L19)(7.4N)

Notes: Domestic - 2 or 4 bolt main, unleaded fuel only. On all 76 models and 77-85 P3 (42) models, a new shallow oil pump, p/n 14067529, must be installed

Replaces: 14105965

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12339194

454 CID Reman

Leaded Fuel Only
7.4L

1974-80	Chevrolet, GMC	C2,3 (454S) NM8
1980-86	Chevrolet, GMC	C2 CK3 (LE8)(454W) NM8
1987-90	Chevrolet, GMC	R2,3 (L19)(7.4N) NM8
1987-89	Chevrolet, GMC	RV2,3 (LE8)(454W) NM8
1988-90	Chevrolet, GMC	CK3 G3 (L19)(7.4N)
1990	Chevrolet	C1 (L19)(7.4N)

Notes: Leaded fuel only. 2-bolt or 4-bolt design. On all 76 models and 77-85 P3 (42) models, a new shallow oil pump, p/n 14067529, must be installed

INSTALLATION INSTRUCTIONS

All 1976 through 1990 C, K G P 123 trucks originally manufactured with 454 engines with the following restrictions:

- Remanufactured engine may be 2 or 4 bolt design.
- Not recommended for high-performance use.
- 1977 through 1985 P3 (42) models have shallow oil pan. For these models, new pump part number 14067529 must be installed in place of the pump supplied with the engine.
- 1990 production engines use ESC knock sensor. Remanufactured engines must be modified for use on 1990 vehicles by tapping the dipstick tube-mounting hole to 1/4-18 dry-seal pipe thread sealer for ESC sensor assembly.

12353125

454 CID Reman

7.4L

1982-86	Chevrolet, GMC	C2 (LE8)(7.4L)
1982-86	Chevrolet, GMC	CK3 (LE8)(7.4L)
1987-88	Chevrolet, GMC	V3 (L19)(7.4L)
1987-89	Chevrolet, GMC	RV2,3 (LE8)
1987-90	Chevrolet, GMC	R2,3 (L19)(7.4L)
1988-90	Chevrolet, GMC	G3 (L19)(7.4L)
1988-90	Chevrolet, GMC	CK3 (L19)(7.4L)
1990	Chevrolet, GMC	C1 (L19)(7.4L)

Notes: On vehicles with shallow oil pan design, a new oil pump, p/n 14067529 with shorter pick tube, must be installed (1977-83 P3 models). 4-bolt main caps, crank and rod bearings are 0.010 oversize max.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88890529

454 CID New

7.4L

1974-86	Chevrolet, GMC	C2,3 K3 (LE8)-454N (LF8)-454W
1984-93	Chevrolet, GMC	P3 (LE8)(LF8)(L19) KC4
1987-91	Chevrolet, GMC	R2,3 (L19)(LE8)
1987-91	Chevrolet, GMC	V3 (L19)(LE8)
1988-93	Chevrolet, GMC	CK1,2,3 (L19)
1988-93	Chevrolet, GMC	G3 (L19)-454N

Engine-Specific Content: Crankshaft Balancer, Front Cover, Oil Fill Cap, Oil Pan, Oil Pump w/Screen, Oil Pump Drive Shaft, Valve Rocker Cover

Notes: Does not use old oil adapter. Cooler lines go to block.

Replaces: 12531454, 10181230

Replaced By:

INSTALLATION INSTRUCTIONS

- All part number 88890529, Goodwrench 7.4 Liter engine assembly, has been developed as a service replacement engine for 1974-1993 light duty truck 454 C.I.D. engine applications.
- When using this engine to replace 1990 and prior applications, the following kits are required:

<u>Retrofit Kit</u>	<u>Model</u>	<u>Year</u>	<u>Restriction</u>
15637091	C1,3	1988-90	Automatic Transmission
15637092	K3	1988-90	Automatic Transmission
15637093	C3	1988-90	Manual Transmission
15637094	K3	1988-90	Manual Transmission
15637099	G3	1988-90	All (w/Oil Cooling)
15637100	P3 (32)	1974-90	w/A.T.
15637101	P3 (32)	1974-90	w/A.T.
15637105	P2,3	1987-90	w/M.T.
15637105	C2,3	1974-86	w/M.T.
15637106	R2,3	1987-90	w/A.T.
15637106	C2,3	1974-86	w/A.T.
15637107	V3	1987-90	w/M.T.
15637107	K3	1974-86	w/M.T.
15637108	V3	1987-90	w/A.T.
15637108	K3	1974-86	w/A.T.

<u>Oil Cooling Kit</u>	<u>Model</u>	<u>Year</u>	<u>Restriction</u>
15637095	CK3	1988-90	KC4 &SA5, SA6
15637096	C1	1990	KC4 (Exc. SA5, SA6)
15637096	CK1	1988-90	KC4 (Exc. SA5, SA6)
15637102	P3 (42)	1987-90	KC4
15637103	P3 (32)	1987-90	KC4 & EN2
15637104	P3 (32)	1987-90	KC4 &EN
15637104	P3 (32)	1984-86	KC4
15637109	R2,3	1987-90	KC4
15637109	C2,3	1983-87	KC4
15637109	C2,3	1974-82	KC4*
15637110	V3	1987-90	KC4
15637110	K3	1983-86	KC4
15637110	K3	1974-82	KC4*

*oil cooler part number 3053355 is required.

- This engine is built to production point of build torque specifications; loss of some torque is normal. It is not necessary to retorquing any bolts.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88890530

454 CID New

7.4L

1994-95	Chevrolet, GMC	CK2,3 (L19)(7.4N) MT1, MT8, MW3
1994-96	Chevrolet, GMC	G3 (L19)(7.4N) MT1
1994-97	Chevrolet, GMC	P3 (L19)(7.4N) MT1

Engine-Specific Content: Crankshaft Balancer, Front Cover, Oil Fill Cap, Oil Pan, Oil Pump w/Screen, Oil Pump Drive Shaft, and Valve Rocker Covers

Replaces: 12530454, 12524681**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88890531

454 CID New

7.4L

1996-2000	Chevrolet, GMC	CK2,3, G3 (L29)(7.4J) MT1, MW3
1996-99	Chevrolet, GMC	P3 (L29) MT1

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, Valve Rocker Covers, and Harmonic Balancer

Replaces: 12534454**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88890532

454 CID New

7.4L

1998-99	Chevrolet, GMC	P3 (L21) MT9, NB6, NF2
1999-2000	Chevrolet, GMC	C6,7 B7 (LP4)(L21)

Engine-Specific Content: Oil Pan, Oil Filter, Front Cover, Valve Rocker Covers, and Harmonic Balancer

Replaces: 12457454, 12456454**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017263 496 CID New **8.1L**

2001-03 Chevrolet, GMC CK2,3 (L18)
2001-02 Chevrolet, GMC G3 (L18)

Replaces: 12568410, 88894037, 88894283,
88894285, 89017231 **Replaced By:** 89017488, 89017594

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017265 496 CID New **8.1L**

2001-02 Chevrolet, GMC B7 (L18)
2001-02 Chevrolet, GMC C6,7 (L18)
2002-03 Chevrolet, GMC C6HO,7HO (L18)
2003 Chevrolet, GMC C6,7,8 (L18)

Replaces: 12568414, 88894038, 88894284,
88894286, 89017233 **Replaced By:** 89017487, 89017595

Notes: 2002 and previous MY, transfer harmonic balancer, valve covers, spark plug wire harness, ignition coils, and ignition coil harness.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017426 496 CID New **8.1L**

2003-04 Chevrolet, GMC C4,5 (L18) ML6, MTX, M74

Replaces: 89017264, 89017232, 88894380 **Replaced By:** 89017486

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

89017487 496 CID New **8.1L**

2001-02 Chevrolet, GMC B7 (L18)
2001-02 Chevrolet, GMC C6,7 (L18)
2002-03 Chevrolet, GMC C6HO,7HO (L18)
2003-04 Chevrolet, GMC C6,7,8 (L18)

Replaces: 12568414, 88894038, 88894284,
88894286, 89017233, 89017265,
89017427 **Replaced By:** 89017595

Notes: 2002 and previous MY, transfer harmonic balancer, valve covers, spark plug wire harness, ignition coils, and ignition coil harness.

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

89017488

496 CID New

8.1L

2001-02	Chevrolet, GMC	G3 (L18)
2001-02	Chevrolet, GMC	CK2,3 (L18) NM2
2001	Chevrolet, GMC	CK2,3 (L18) NB6, NF2, NC1
2002-04	Chevrolet, GMC	CK2,3 (L18)
2003	Chevrolet, GMC	CK2,3 (L18) MN8, M74
2003-04	Chevrolet, GMC	C314 (L18)

Replaces: 12568410, 88894037, 88894283,
88894285, 89017231, 89017263,
88894039, 89017428

Replaced By: 89017594

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

V8 Engine Family Diesel

APPLICATION, CONTENT & INSTALLATION PROCEDURES

GOODWRENCH SERVICE REPLACEMENT ENGINES

12457636 395 CID New **6.5L**

1997-98 Chevrolet, GMC B7 (L65)

Replaces: **Replaced By:** 88894129

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

12457637 395 CID New **6.5L**

1996 Chevrolet, GMC G2,3 (L65)(6.5F)

Replaces: **Replaced By:** 88894127

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894125 395 CID New **6.5L**

1994-96 Chevrolet, GMC CK1,2,3 P3 (L65)
1996 Chevrolet, GMC P3 (L65) MF1, MT9

Notes: On models without crankshaft sensor, plug hole at lower left-hand corner with part number 10231255. For 1996 and prior with .375 THD for oil cooler hose, use connector part number 12554978

Replaces: 12457640 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894126 395 CID New **6.5L**

1997-99 Chevrolet, GMC P3 (L65) MT1, NA7, NB6, NF2
1997-99 Chevrolet, GMC CK1,2,3 (L65)
2000 Chevrolet, GMC CK2,3 (L65)
2001-02 Chevrolet, GMC C310,314,318 (L65)

Replaces: 12457641 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894128 395 CID New **6.5L**

1997-2001 Chevrolet, GMC G2,3 (L65) MT1

Replaces: 12457638 **Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894130

395 CID New

6.5L

1982-86	Chevrolet, GMC	CK1,2 (6.5L)
1983-93	Chevrolet, GMC	G2,3 (6.5L)
1988-91	Chevrolet, GMC	CK1,2,3 (6.5L)
1992-93	Chevrolet, GMC	CK1,2,3 (LH6)(LL4)
1994-95	Chevrolet, GMC	CK1,2, (L49)(L56) MT8, M30, MT1
1994-95	Chevrolet, GMC	G2 (L49) M30, NA5, NA6, NB2
1994	Chevrolet, GMC	G3 (L57) MT1, NA5, NB2
1995-96	Chevrolet, GMC	CK1,2 G3 (L56)
1997	Chevrolet, GMC	CK1,2 (L56) MT1, NF2

Notes: On models without crankshaft sensor, plug hole at lower left-hand corner with part number 10231255. For 1996 and prior with .375 THD for oil cooler hose, use connector part number 12554978

Replaces: 12457643, 12456104**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894131

395 CID New

6.5L

1998	Chevrolet, GMC	CK1,2, (L56) MT1, NF2
------	----------------	-----------------------

Replaces: 12457642**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

88894132

395 CID New

6.5L

1999	Chevrolet, GMC	P3 (L57) C7A, NB6
1998	Chevrolet, GMC	P3 (L57) MW3, MT1, C7A, C7E, NB6

Replaces: 12457645**Replaced By:**

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.

GOODWRENCH SERVICE REPLACEMENT ENGINES

88894133

395 CID New

6.5L

1999	Chevrolet, GMC	P3 (L57) C7E, C7M, C7P, C7S, NB6
1999	Chevrolet, GMC	P3 (L57) NF2, NA6
1998	Chevrolet, GMC	P3 (L57) MT1, MW3
1991-98	Chevrolet, GMC	P3 (L57)
1982-90	Chevrolet, GMC	P3 (6.5L)

Engine-Specific Content: Balancer and Oil Pan

Notes: On models without crankshaft sensor, plug hole at lower left-hand corner with part number 10231255. For 1996 and prior with .375 THD for oil cooler hose, use connector part number 12554978

Replaces: 12457644

Replaced By:

INSTALLATION INSTRUCTIONS

No special installation instructions are necessary. Please refer to the general installation procedure section of this book.



PART NUMBER INDEX

Part Number	Liter	CID	Section	Page
10054502	2.8	173	VII	37
10067353	5.7	350	VII	86
12339193	7.4	454	VII	102
12339194	7.4	454	VII	102
12339196	7.0	427	VII	100
12339198	6.0	366	VII	95
12351901	2.5	151	VII	13
12351904	2.5	151	VII	14
12351905	2.5	151	VII	15
12351906	2.5	151	VII	16
12351907	2.5	151	VII	17
12351909	2.5	151	VII	18
12351910	2.5	151	VII	19
12351911	2.5	151	VII	20
12351912	2.5	151	VII	21
12351913	2.5	151	VII	22
12351914	2.5	151	VII	23
12351915	2.5	151	VII	24
12351917	2.5	151	VII	25
12351918	2.5	151	VII	26
12351919	2.5	151	VII	27
12351920	2.5	151	VII	28
12351921	2.5	151	VII	29
12351923	2.5	151	VII	30
12351924	2.5	151	VII	31
12353125	7.4	454	VII	102
12356519	3.3	204	VII	43
12356520	3.3	204	VII	43
12356521	3.3	204	VII	43
12356522	3.3	204	VII	44
12356523	3.3	204	VII	44
12360021	3.8	231	VII	50
12360022	3.8	231	VII	50
12360023	3.8	231	VII	51
12360467	2.4	146	VII	12
12360619	2.3	138	VII	6
12360620	2.3	138	VII	6
12360623	2.3	138	VII	7
12360624	2.3	138	VII	7
12360625	2.3	138	VII	8
12360626	2.3	138	VII	8
12360627	2.3	138	VII	9
12360686	3.8	231	VII	51
12360687	3.8	231	VII	51
12361241	4.3	262	VII	59
12361243	4.3	262	VII	60
12361247	4.3	262	VII	61
12361248	4.3	262	VII	61
12361249	4.3	262	VII	62



PART NUMBER INDEX

Part Number	Liter	CID	Section	Page
12361251	4.3	262	VII	62
12361252	4.3	262	VII	63
12361253	4.3	262	VII	63
12361504	2.3	138	VII	9
12362213	3.8	231	VII	52
12362214	3.8	231	VII	52
12362215	3.8	231	VII	53
12362216	3.8	231	VII	53
12362217	3.8	231	VII	54
12362218	3.8	231	VII	54
12362219	3.8	231	VII	54
12362220	3.8	231	VII	55
12362221	3.8	231	VII	55
12363193	2.2	133	VII	2
12363194	2.2	133	VII	2
12363195	2.2	133	VII	2
12363728	4.3	262	VII	64
12363729	4.3	262	VII	64
12363730	4.3	262	VII	65
12366016	4.3	262	VII	65
12366017	4.3	262	VII	66
12369214	4.3	262	VII	66
12369568	4.6	280	VII	79
12371987	3.1	191	VII	39
12455109	5.7	350	VII	86
12457636	6.5	395	VII	108
12457637	6.5	395	VII	108
12457660	5.7	350	VII	87
12457703	4.8	292	VII	82
12457704	4.8	292	VII	82
12457705	5.3	323	VII	85
12457706	6.0	366	VII	95
12458123	3.5	214	VII	48
12458124	3.5	214	VII	48
12462258	2.4	146	VII	12
12465229	6.0	366	VII	96
12465411	2.2	133	VII	3
12465434	2.2	133	VII	3
12465435	2.2	133	VII	3
12465447	2.2	133	VII	3
12465498	2.4	146	VII	12
12480240	3.1	191	VII	39
12480242	3.1	191	VII	39
12481315	3.8	231	VII	56
12482057	3.8	231	VII	56
12507648	2.8	173	VII	37
12513151	5.7	350	VII	87
12513152	3.1	191	VII	39
12513153	3.1	191	VII	40



PART NUMBER INDEX

Part Number	Liter	CID	Section	Page
12515469	4.3	262	VII	67
12518296	5.0	305	VII	83
12518298	5.0	305	VII	83
12520270	5.7	350	VII	88
12522927	3.1	191	VII	40
12522928	3.1	191	VII	41
12523277	2.8	173	VII	38
12523279	2.8	173	VII	38
12530282	5.7	350	VII	88
12530283	5.7	350	VII	88
12530284	5.0	305	VII	84
12530427	7.0	427	VII	100
12532427	7.0	427	VII	101
12534776	5.7	350	VII	89
12537812	3.4	207	VII	45
12539087	3.1	191	VII	41
12567312	4.0	244	VII	77
12567313	4.6	280	VII	79
12567314	4.6	280	VII	79
12567316	4.6	280	VII	80
12568758	5.7	350	VII	89
12568759	5.7	350	VII	89
12569010	5.7	350	VII	89
12569068	5.7	350	VII	90
12585215	2.8	173	VII	33
12585341	3.5	214	VII	35
12585342	3.5	214	VII	35
12593224	2.2	133	VII	4
12593292	2.2	133	VII	4
12593699	3.6	214	VII	49
12593700	3.6	214	VII	49
12595157	3.6	214	VII	49
22538277	5.0	305	VII	84
24571996	2.3	138	VII	10
24573746	2.3	138	VII	10
24575362	2.3	138	VII	11
88890529	7.4	454	VII	103
88890530	7.4	454	VII	104
88890531	7.4	454	VII	104
88890532	7.4	454	VII	104
88890535	6.0	366	VII	97
88893272	4.3	262	VII	68
88893274	4.3	262	VII	69
88893275	4.3	262	VII	70
88893276	4.3	262	VII	70
88893286	5.7	350	VII	90
88893287	5.7	350	VII	90
88893289	4.8	292	VII	82
88893290	4.8	292	VII	82



PART NUMBER INDEX

Part Number	Liter	CID	Section	Page
88893291	5.3	323	VII	85
88894033	3.4	207	VII	45
88894034	3.4	207	VII	45
88894086	5.7	350	VII	90
88894110	3.1	191	VII	41
88894112	3.1	191	VII	42
88894118	4.3	262	VII	71
88894125	6.5	395	VII	108
88894126	6.5	395	VII	108
88894128	6.5	395	VII	108
88894130	6.5	395	VII	109
88894131	6.5	395	VII	109
88894132	6.5	395	VII	109
88894133	6.5	395	VII	109
88894187	2.2	134	VII	4
88894189	2.2	134	VII	4
88894191	4.3	262	VII	78
88894192	4.3	262	VII	78
88894193	5.7	350	VII	90
88894194	5.7	350	VII	91
88894195	5.7	350	VII	91
88894196	5.7	350	VII	92
88894197	5.7	350	VII	92
88894238	4.0	244	VII	77
88894239	4.6	280	VII	80
88894240	4.6	280	VII	80
88894249	4.6	280	VII	80
88894250	4.6	280	VII	80
88894384	5.7	350	VII	93
88984238	4.2	256	VII	75
88984244	2.2	134	VII	5
88984251	3.4	207	VII	46
88984253	4.6	280	VII	81
88984254	4.6	280	VII	81
88984255	4.0	244	VII	77
88984287	3.4	207	VII	46
88984288	3.4	207	VII	46
89017263	8.1	496	VII	105
89017265	8.1	496	VII	105
89017321	4.3	262	VII	71
89017323	4.3	262	VII	72
89017324	4.3	262	VII	72
89017325	4.3	262	VII	72
89017331	4.3	262	VII	73
89017349	5.7	350	VII	93
89017352	5.7	350	VII	93
89017353	4.8	292	VII	82
89017354	5.3	323	VII	85
89017355	5.3	323	VII	85

PART NUMBER INDEX

Part Number	Liter	CID	Section	Page
89017356	6.0	366	VII	98
89017357	6.0	366	VII	98
89017358	6.0	366	VII	98
89017359	6.0	366	VII	98
89017411	4.6	280	VII	81
89017416	3.8	231	VII	57
89017426	8.1	496	VII	105
89017444	3.4	207	VII	46
89017445	3.4	207	VII	47
89017446	4.6	280	VII	81
89017447	4.6	280	VII	81
89017454	3.1	191	VII	42
89017487	8.1	496	VII	105
89017488	8.1	496	VII	106
89017548	5.7	350	VII	93
89017653	5.7	350	VII	94
89017654	6.0	366	VII	99
89017667	3.8	231	VII	57
89017669	3.8	231	VII	58
89017670	3.8	231	VII	58
89037576	3.1	191	VII	42
89038378	3.1	191	VII	42
89038381	3.4	207	VII	47
89038382	3.4	207	VII	47
89038385	3.4	207	VII	47



COMMENTS & FEEDBACK

**We welcome your comments and feedback about this guide.
Please complete this form and fax to the number below.**

Date: _____

From: _____

To: Goodwrench Engines

Dealer: _____

Fax: (810) 606-3250

Phone: _____

Re: **2004 Goodwrench Engine Reference Guide**

Comments / Feedback:

[illegible]

☐ **Please contact me.**